| Unique ID # | Street Address | Utility-Owned Service Line Material | Service Line Installation Year | Service Line Size | Basis of Material Classification | Customer- Owned Service Line Material | Service Line Installation Date | Service Line Size | Basis of Material Classification | Entire Service Line |
|----------------------|----------------------------|---|--------------------------------------|----------------------|---|--|--------------------------------------|----------------------|--|------------------------|
| | | | | | | | | | | |
| SV HAWL 47 | 47 Hawley Ln. | Non-Lead - Copper | 5/14/2004 | 1 | Installation record | Non-Lead - HDPE | 5/14/2004 | 1 | Installation record | Non-Lead |
| SV HAWL 49 | 49 Hawley Ln. | Non-Lead - Copper | 9/1/2003 | 1 | Installation record | Non-Lead - Other | 9/1/2003 | 1 | Installed after 1989 -AK lead ban | Non-Lead |
| SV HAWL 53 | 53 Hawley Ln. | Non-Lead - Other | 4/25/1994 | 3/4 | Installed after 1989 -AK lead ban | Non-Lead - Other | 4/25/1994 | 3/4 | Installed after 1989 -AK lead ban | Non-Lead |
| SV BRDE 2051 | 2051 East Broadway Ave. | Non-Lead - Copper | 8/12/1995 | 3/4 | Installation record | Non-Lead - Other | 8/12/1995 | 3/4 | Installed after 1989 -AK lead ban | Non-Lead |
| SV BRDE 1999 | 1999 East Broadway Ave. | Non-Lead - Copper | 3/30/1996 | 3/4 | Installation record | Non-Lead - Other | 3/30/1996 | 3/4 | Installed after 1989 -AK lead ban | Non-Lead |
| SV HAWL 25 | 25 Hawley Ln. | Non-Lead - Copper | | | Repair / replacement record | Non-Lead - Copper | | | Repair / replacement record | Non-Lead |
| STUB BRDE 1980 | 1980 East Broadway Ave. | Non-Lead - Copper | | | Repair / replacement record | N/A | | | N/A | Non-Lead |
| SV BRDE 1975/1977 | 1977 East Broadway Ave. | Non-Lead - Copper | 4/1/1997 | 1 | Installation record | Non-Lead - Other | 4/1/1997 | 1 | Installed after 1989 -AK lead ban | Non-Lead |
| SV BRDE 1950 | 1950 East Broadway Ave. | Non-Lead - Copper | | 3/4 | Installation record | Non-Lead - HDPE | | 3/4 | Field inspection only (no records) | Non-Lead |
| STUB BRDE 1970 | 1970 East Broadway Ave. | Non-Lead - Copper | | 3/4 | Installation record | N/A | | | N/A | Non-Lead |
| SV BRDE 1937 | 1937 East Broadway Ave. | Non-Lead - Copper | 10/28/2002 | 1 | Installation record | Non-Lead - Other | 10/28/2002 | 1 | Installed after 1989 -AK lead ban | Non-Lead |

| SV BRDE 1936 | 1936 East Broadway Ave. | Non-Lead - Copper | | 3/4 | Installation record | Non-Lead - Other | | 3/4 | Installed after 1989 -AK lead ban | #N/A |
|-------------------|----------------------------|----------------------|------------|-----|---|----------------------|------------|-----|---|----------|
| STUB BRDE 1934 | 1934 East Broadway Ave. | Non-Lead - Copper | | | Other - describe in notes | N/A | | | N/A | Non-Lead |
| STUB BRDE 1932 | 1932 East Broadway Ave. | Non-Lead - Copper | | | Other - describe in notes | N/A | | | N/A | Non-Lead |
| SV HAWL 69 | 69 Hawley Ln. | Non-Lead - Copper | 10/28/2002 | 1 | Installation record | Non-Lead - HDPE | 10/28/2002 | 1 | Installation record | #N/A |
| SV BRDE 1930 | 1930 East Broadway Ave. | Non-Lead - Copper | | 3/4 | Installation record | Non-Lead - Copper | | 3/4 | Repair / replacement record | Non-Lead |
| SV BRDE 1926 | 1926 East Broadway Ave. | Non-Lead - Copper | | 3/4 | Installation record | Non-Lead - Copper | | 3/4 | Repair / replacement record | Non-Lead |
| SV BRDE 1914 | 1914 East Broadway Ave. | Non-Lead - Copper | | | Installation record | Non-Lead - HDPE | | | Installation record | #N/A |
| SV BRDE 1905 | 1905 East Broadway Ave. | Non-Lead - Copper | | | Interpolation/ statistical analysis | Non-Lead - Copper | | | Field inspection only (no records) | #N/A |
| SV STEW 669 | 669 Steward Rd. | Non-Lead - Copper | | | Field inspection only (no records) | Non-Lead - Other | | | Field inspection only (no records) | Non-Lead |
| SV BRDE 1857 | 1857 East Broadway Ave. | Non-Lead - Copper | 11/16/1998 | 3/4 | Installation record | Non-Lead - Other | | | Installed after 1989 -AK lead ban | Non-Lead |
| SV OVER 10 | 10 Overland Dr. | Non-Lead - Copper | 10/1/1997 | 3/4 | Installation record | Non-Lead - Other | | | Installed after 1989 -AK lead ban | Non-Lead |
| SV BRDE 1851 | 1851 East Broadway Ave. | Non-Lead - Copper | | 1 | Installation record | Non-Lead - Copper | | 3/4 | Installed after 1989 -AK lead ban | Non-Lead |
| SV OVER 18 | 18 Overland Dr. | Non-Lead - Copper | 10/10/2014 | 3/4 | Installation record | Non-Lead - HDPE | 10/10/2014 | 3/4 | Installation record | Non-Lead |

| SV CHOA 43 | 43 Choate Ln. | Non-Lead - Copper | 8/13/1999 | 3/4 | Installation record | Non-Lead - Copper | | 3/4 | Other - describe in notes | Non-Lead |
|--------------------|---------------------|----------------------|------------|-----|------------------------|----------------------|------------|-----|---|----------|
| SV CHOA 48/50 | 48 Choate Ln. | Non-Lead - Copper | 5/27/1999 | 3/4 | Installation record | Non-Lead - Other | | 3/4 | Installed after 1989 -AK lead ban | Non-Lead |
| SV CHOA 47 | 47 Choate Ln. | Non-Lead - Copper | 7/28/2000 | 3/4 | Installation record | Non-Lead - Other | | 3/4 | Installed after 1989 -AK lead ban | Non-Lead |
| SV CHOA 55 | 55 Choate Ln. | Non-Lead - Copper | 11/1/2023 | 1 | Installation record | Non-Lead - Copper | 11/1/2023 | 1 | Installation record | Non-Lead |
| SV CHOA 57 | 57 Choate Ln. | Non-Lead - Copper | 11/1/2023 | 3/4 | Installation record | Non-Lead - Copper | 11/1/2023 | 3/4 | Installation record | Non-Lead |
| SV CHOA 62 | 62 Choate Ln. | Non-Lead - Copper | 4/7/2004 | 1 | Installation record | Non-Lead - Other | 4/7/2024 | 1 | Installed after 1989 -AK lead ban | Non-Lead |
| SV CHOA 79 | 79 Choate Ln. | Non-Lead - Copper | 10/1/1997 | 3/4 | Installation record | Non-Lead - Other | 10/1/1997 | 3/4 | Installed after 1989 -AK lead ban | Non-Lead |
| SV CHOA 92/94 | 92 Choate Ln. | Non-Lead - Copper | 9/20/2007 | 1 | Installation record | Non-Lead - HDPE | 9/20/2007 | 1 | Other - describe in notes | Non-Lead |
| SV CHOA 102/104 | 102 Choate Ln. | Non-Lead - Copper | 10/30/1998 | 1 | Installation record | Non-Lead - Other | 10/30/1998 | 1 | Installed after 1989 -AK lead ban | Non-Lead |
| SV OVER 122 | 122 Overland Dr. | Non-Lead - Copper | 7/23/1999 | 3/4 | Installation record | Non-Lead - HDPE | 7/23/1999 | 3/4 | Installation record | Non-Lead |
| SV CHOA 107 | 107 Choate Ln. | Non-Lead - Copper | 10/1/1997 | 3/4 | Installation record | Non-Lead - Other | 10/1/1997 | 3/4 | Installed after 1989 -AK lead ban | Non-Lead |
| SV CHOA 133 | 133 Choate Ln. | Non-Lead - Copper | | 3/4 | Installation record | Non-Lead - Copper | | 3/4 | Other - describe in notes | Non-Lead |
| SV OVER 148 | 148 Overland Dr. | Non-Lead - Copper | | 3/4 | Installation record | Non-Lead - Copper | | 3/4 | Repair / replacement record | Non-Lead |

| SV CHOA 149 | 149 Choate Ln. | Non-Lead - Copper | 4/8/2021 | 3/4 | Installation record | Non-Lead - Copper | 4/8/2021 | 3/4 | Other - describe in notes | Non-Lead |
|----------------------|----------------------------|----------------------|------------|-------|------------------------------------|----------------------|------------|-------|--|----------|
| SV OVER 150 | 150 Overland Dr. | Non-Lead - Copper | 11/27/2017 | 3/4 | Installation record | Non-Lead - HDPE | 11/27/2017 | 3/4 | Installation record | Non-Lead |
| SV CHOA 164 | 164 Choate Ln. | Non-Lead - Copper | 7/27/2001 | 1 | Installation record | Non-Lead - Other | 7/27/2001 | 1 | Installed after 1989 -AK lead ban | Non-Lead |
| SV CHOA 169/171 | 169 Choate Ln. | Non-Lead - Copper | 9/18/1998 | 1 | Installation record | Non-Lead - Other | 9/18/1998 | 1 | Installed after 1989 -AK lead ban | Non-Lead |
| SV OVER 93 | 93 Overland Dr. | Non-Lead - Copper | | 1 | Installation record | Non-Lead - Copper | | 1 | Repair / replacement record | Non-Lead |
| SV BRDE 1757 | 1757 East Broadway Ave. | Non-Lead - Copper | | 2 | Repair / replacement record | Non-Lead - Copper | | 2 | Field inspection only (no records) | Non-Lead |
| SV BRDE 1750 | 1750 East Broadway Ave. | Non-Lead - Copper | | 2 | Installation record | Non-Lead - Copper | | 2 | Installation record | Non-Lead |
| STUB BRDE 1747 | 1747 East Broadway Ave. | Non-Lead - Copper | | 3/4 | Repair / replacement record | N/A | | | N/A | Non-Lead |
| SV BRDE 1715 | 1715 East Broadway Ave. | Non-Lead - Copper | 5/12/1993 | 3/4 | Installation record | Non-Lead - Other | 5/12/1993 | 3/4 | Installed after 1989 -AK lead ban | Non-Lead |
| SV BRDE 1713 | 1713 East Broadway Ave. | Non-Lead - Copper | 4/9/1993 | 3/4 | Installation record | Non-Lead - Copper | 4/9/1993 | 3/4 | Other - describe in notes | Non-Lead |
| SV BRDE 1661 | 1661 East Broadway Ave. | Non-Lead - Copper | | | Field inspection only (no records) | Non-Lead - Copper | | | Field inspection only (no records) | Non-Lead |
| SV BRDE 1588 | 1588 East Broadway Ave. | Non-Lead - Copper | 5/25/2001 | 1 1/2 | Installation record | Non-Lead - Other | 5/25/2001 | 1 1/2 | Installed after 1989 -AK lead ban | Non-Lead |
| SV BRDE 1563/1565 | 1563 East Broadway Ave. | Non-Lead - Copper | 6/13/2014 | 1 | Installation record | Non-Lead - HDPE | 6/13/2014 | 1 | Other - describe in notes | #N/A |

| SV BRDE 1559 | 1559 East Broadway Ave. | Non-Lead - Copper | | | Installation record | Non-Lead - Other | | | Installed after 1989 -AK lead ban | Non-Lead |
|------------------------------------|----------------------------|----------------------|------------|-----|-----------------------------------|----------------------|------------|-----|---|----------|
| SV BRDE 1487/1497/151 3 | 1487 East Broadway Ave. | Non-Lead - Copper | 11/20/2001 | 2 | Installation record | Non-Lead - Copper | 11/20/2001 | 2 | Installation record | Non-Lead |
| SV BRDE 1388/1390/139 8/1400 | 1388 East Broadway Ave. | Non-Lead - Copper | | 1 | Installation record | Non-Lead - Copper | | 1 | Installation record | Non-Lead |
| STUB BRDE 1301 | 1301 East Broadway Ave. | Non-Lead - Copper | | | Repair / replacement record | N/A | | | N/A | Non-Lead |
| SV BRDE 1253 | 1253 East Broadway Ave. | Non-Lead - Copper | 7/14/1988 | 3/4 | Repair / replacement record | Non-Lead - PVC | 7/14/1988 | 3/4 | Repair / replacement record | Non-Lead |
| SV BRDE 1149 | 1149 East Broadway Ave. | Non-Lead - Copper | 4/20/1998 | 2 | Installation record | Non-Lead - Other | 4/20/1998 | 2 | Installed after 1989 -AK lead ban | Non-Lead |
| SV LEAR 62/64 | 62 Lear Rd. | Non-Lead - Copper | 7/11/2000 | 2 | Installation record | Non-Lead - Other | 7/11/2000 | 2 | Installed after 1989 -AK lead ban | Non-Lead |
| SV LEAR 69/73/81/85 | 69 Lear Rd. | Non-Lead - Copper | | 2 | Repair / replacement record | Non-Lead - HDPE | | 2 | Repair / replacement record | Non-Lead |
| SV LEAR 102 | 102 Lear Rd. | Non-Lead - Copper | 8/1/1997 | 3/4 | Installation record | Non-Lead - Other | 8/1/1997 | 3/4 | Installed after 1989 -AK lead ban | #N/A |
| SV LEAR 114 | 114 Lear Rd. | Non-Lead - Copper | 10/30/1998 | 3/4 | Installation record | Non-Lead - Other | 10/30/1998 | 3/4 | Installed after 1989 -AK lead ban | Non-Lead |
| SV LEAR 124 | 124 Lear Rd. | Non-Lead - Copper | 9/5/1997 | 3/4 | Installation record | Non-Lead - Other | 9/5/1997 | 3/4 | Installed after 1989 -AK lead ban | Non-Lead |
| SV LEAR 128 | 128 Lear Rd. | Non-Lead - Copper | 5/1/2010 | | Installation record | Non-Lead - Other | 5/1/2010 | | Installed after 1989 -AK lead ban | Non-Lead |
| SV Lear 176 | 176 Lear Rd. | Non-Lead - Copper | 10/23/1998 | 1 | Installation record | Non-Lead - Other | 10/23/1998 | 1 | Installed after 1989 -AK lead ban | Non-Lead |

| SV BRDE 1138 | 1138 East Broadway Ave. | Non-Lead - Copper | 8/1/1989 | 1 | Repair / replacement record | Non-Lead - Copper | 8/1/1989 | 1 | Other - describe in notes | Non-Lead |
|----------------------|----------------------------|----------------------|------------|-------|-----------------------------------|----------------------|------------|-------|---|----------|
| SV BRDE 1080/1084 | 1080 East Broadway Ave. | Non-Lead - Copper | | 1 1/2 | Installation record | Non-Lead - HDPE | | 1 1/2 | Installation record | Non-Lead |
| SV BRDE 1059 | 1059 East Broadway Ave. | Non-Lead - Copper | 10/17/2003 | 2 | Installation record | Non-Lead - Copper | 10/17/2003 | 2 | Other - describe in notes | Non-Lead |
| SV BRDE 997 | 997 East Broadway Ave. | Non-Lead - Copper | 6/5/1995 | 1 1/2 | Installation record | Non-Lead - Copper | 6/5/1995 | 1 1/2 | Other - describe in notes | Non-Lead |
| SV STEW 660 | 660 Steward Rd. | Non-Lead - Copper | | 3/4 | Installation record | Non-Lead - Copper | | 3/4 | Repair / replacement record | Non-Lead |
| SV STEW 640 | 640 Steward Rd. | Non-Lead - Copper | 8/1/2012 | 3/4 | Installation record | Non-Lead - Other | 8/1/2012 | 3/4 | Installed after 1989 -AK lead ban | Non-Lead |
| SV STEW 629 | 629 Steward Rd. | Non-Lead - Copper | 7/17/2000 | 1 | Installation record | Non-Lead - Copper | 7/17/2000 | 1 | Installation record | Non-Lead |
| SV STEW 611 | 611 Steward Rd. | Non-Lead - Copper | 4/23/1998 | 3/4 | Installation record | Non-Lead - Other | 4/23/1998 | 3/4 | Installed after 1989 -AK lead ban | Non-Lead |
| STUB STEW 614 | 614 Steward Rd. | Non-Lead - Copper | 10/31/2002 | 1 | Installation record | N/A | | | N/A | Non-Lead |
| SV STEW 581 | 581 Steward Rd. | Non-Lead - Copper | 9/6/2002 | 3/4 | Installation record | Non-Lead - Other | 9/6/2002 | 3/4 | Installed after 1989 -AK lead ban | Non-Lead |
| STUB STEW 594 | 594 Steward Rd. | Non-Lead - Copper | 10/31/2002 | 1 | Installation record | N/A | | | N/A | Non-Lead |
| SV STEW 572 | 572 Steward Rd. | Non-Lead - Copper | 9/14/1995 | | Installation record | Non-Lead - Other | 9/14/1995 | | Installed after 1989 -AK lead ban | Non-Lead |
| SV STEW 557/559 | 557 Steward Rd. | Non-Lead - Copper | 7/15/1994 | 1 | Installation record | Non-Lead - Other | 7/15/1994 | 1 | Installed after 1989 -AK lead ban | Non-Lead |

| SV STEW 550 | 550 Steward Rd. | Non-Lead - Copper | | | Field inspection only (no records) | Non-Lead - Other | | | Field inspection only (no records) | #N/A |
|--------------------|--------------------|----------------------|------------|-----|---|----------------------|------------|-----|--|----------|
| SV STEW 495/497 | 495 Steward Rd. | Non-Lead - Copper | 4/17/2019 | 1 | Installation record | Non-Lead - Copper | 4/17/2019 | 3/4 | Other - describe in notes | Non-Lead |
| SV STEW 479 | 479 Steward Rd. | Non-Lead - Copper | 9/14/2004 | 3/4 | Installation record | Non-Lead - Other | 9/14/2004 | 3/4 | Installed after 1989 -AK lead ban | #N/A |
| SV STEW 431 | 431 Steward Rd. | Non-Lead - Copper | 2/23/2005 | 3/4 | Installation record | Non-Lead - Other | 2/23/2005 | 3/4 | Installed after 1989 -AK lead ban | Non-Lead |
| SV STEW 405 | 405 Steward Rd. | Non-Lead - Copper | 10/24/2002 | 1 | Installation record | Non-Lead - HDPE | 10/24/2002 | 1 | Installation record | Non-Lead |
| SV STEW 448 | 448 Steward Rd. | Non-Lead - Copper | 8/1/2000 | 3/4 | Installation record | Non-Lead - Other | 8/1/2000 | 3/4 | Installation record | Non-Lead |
| SV STEW 422/424 | 422 Steward Rd. | Non-Lead - Copper | | | Installation record | Non-Lead - Copper | | | Installation record | Non-Lead |
| SV STEW 376 | 376 Steward Rd. | Non-Lead - Copper | 9/13/1993 | 3/4 | Installation record | Non-Lead - Other | 9/13/1993 | 3/4 | Installed after 1989 -AK lead ban | Non-Lead |
| STUB STEW 370 | 370 Steward Rd. | Non-Lead - Copper | | 3/4 | Interpolation/ statistical analysis | N/A | | | N/A | Non-Lead |
| SV STEW 350 | 350 Steward Rd. | Non-Lead - Copper | 6/1/1992 | 3/4 | Installation record | Non-Lead - Other | 6/1/1992 | 3/4 | Installed after 1989 -AK lead ban | Non-Lead |
| SV STEW 357 | 357 Steward Rd. | Non-Lead - Copper | 12/15/1999 | 1 | Repair / replacement record | Non-Lead - HDPE | 12/15/1999 | 1 | Repair / replacement record | Non-Lead |
| SV STEW 336 | 336 Steward Rd. | Non-Lead - Copper | 6/1/1992 | 3/4 | Installation record | Non-Lead - Copper | 6/1/1992 | 3/4 | Installation record | Non-Lead |
| SV STEW 316 | 316 Steward Rd. | Non-Lead - Copper | 6/1/1992 | | Installation record | Non-Lead - Copper | 6/1/1992 | | Other - describe in notes | Non-Lead |

| SV STEW 296 | 296 Steward Rd. | Non-Lead - Copper | 6/1/1992 | 3/4 | Installation record | Non-Lead - Other | 6/1/1992 | 3/4 | Installed after 1989 -AK lead ban | #N/A |
|--------------------|--------------------|----------------------|------------|-----|------------------------|----------------------|------------|-----|---|----------|
| SV STEW 291/293 | 291 Steward Rd. | Non-Lead - Copper | | 3/4 | Installation record | Non-Lead - Copper | | 3/4 | Field inspection only (no records) | Non-Lead |
| SV STEW 273 | 273 Steward Rd. | Non-Lead - Copper | 7/1/1987 | | Installation record | Non-Lead - Copper | 7/1/1987 | | Field inspection only (no records) | Non-Lead |
| SV STEW 249/257 | 249 Steward Rd. | Non-Lead - Copper | 7/1/1987 | 1 | Installation record | Non-Lead - HDPE | 7/1/1987 | 1 | Installation record | Non-Lead |
| SV STEW 233 | 233 Steward Rd. | Non-Lead - Copper | 7/1/1987 | | Installation record | Non-Lead - Other | 7/1/1987 | | Interpolation/ statistical analysis | Non-Lead |
| SV STEW 207 | 207 Steward Rd. | Non-Lead - Copper | 7/1/1987 | | Installation record | Non-Lead - Copper | 7/1/1987 | | Field inspection only (no records) | Non-Lead |
| SV STEW 187 | 187 Steward Rd. | Non-Lead - Copper | 7/28/1994 | 1 | Installation record | Non-Lead - Other | 7/28/1994 | 1 | Installed after 1989 -AK lead ban | Non-Lead |
| SV STEW 176/184 | 176 Steward Rd. | Non-Lead - Copper | 9/30/1989 | 1 | Installation record | Non-Lead - Copper | 9/30/1989 | 1 | Installation record | Non-Lead |
| SV STEW 169 | 169 Steward Rd. | Non-Lead - Copper | 2/28/1996 | 1 | Installation record | Non-Lead - Other | 2/28/1996 | 1 | Installed after 1989 -AK lead ban | Non-Lead |
| SV STEW 158/160 | 158 Steward Rd. | Non-Lead - Other | 7/28/2010 | 1 | Installation record | Non-Lead - Other | 7/28/2010 | 1 | Installed after 1989 -AK lead ban | Non-Lead |
| SV STEW 140/142 | 142 Steward Rd. | Non-Lead - Copper | 10/31/2013 | 1 | Installation record | Non-Lead - Other | 10/31/2013 | 1 | Installed after 1989 -AK lead ban | Non-Lead |
| SV STEW 141 | 141 Steward Rd. | Non-Lead - Copper | 6/1/1992 | | Installation record | Non-Lead - Other | 6/1/1992 | | Installed after 1989 -AK lead ban | Non-Lead |
| SV STEW 122/124 | 122 Steward Rd. | Non-Lead - Copper | 4/25/1992 | 1 | Installation record | Non-Lead - Other | 4/25/1992 | 1 | Installed after 1989 -AK lead ban | Non-Lead |

| SV STEW 134 | 134 Steward Rd. | Non-Lead - Copper | 5/23/1998 | 1 | Installation record | Non-Lead - HDPE | 5/23/1998 | 1 | Installation record | Non-Lead |
|---------------|---------------------|----------------------|-----------|-----|-----------------------------------|----------------------|-----------|-----|--|----------|
| SV STEW 123 | 123 Steward Rd. | Non-Lead - Copper | 6/1/1992 | 1 | Installation record | Non-Lead - Other | 6/1/1992 | 1 | Installed after 1989 -AK lead ban | Non-Lead |
| SV STEW 90 | 90 Steward Rd. | Non-Lead - Copper | 5/30/2005 | 1 | Installation record | Non-Lead - Copper | 5/30/2005 | 1 | Other - describe in notes | Non-Lead |
| SV STEW 101 | 101 Steward Rd. | Non-Lead - Copper | | 3/4 | Installation record | Non-Lead - Copper | | 3/4 | Field inspection only (no records) | Non-Lead |
| SV STEW 79 | 79 Steward Rd. | Non-Lead - Copper | 7/29/1994 | 3/4 | Installation record | Non-Lead - Copper | 7/29/1994 | 3/4 | Installation record | Non-Lead |
| SV STEW 75 | 75 Steward Rd. | Non-Lead - Copper | 8/1/1996 | 3/4 | Repair / replacement record | Non-Lead - HDPE | 8/1/1996 | 3/4 | Installation record | Non-Lead |
| STUB STEW 70 | 70 Steward Rd. | Non-Lead - Copper | 12/8/2022 | 1 | Installation record | N/A | | | N/A | Non-Lead |
| SV STEW 24 | 24 Steward Rd. | Non-Lead - Copper | 8/1/1996 | 3/4 | Installation record | Non-Lead - Other | 8/1/1996 | 3/4 | Installed after 1989 -AK lead ban | Non-Lead |
| SV EAGD 12 | 12 Eagle Dr. | Non-Lead - Copper | 8/1/1989 | 1 | Installation record | Non-Lead - Copper | 8/1/1989 | 1 | Field inspection only (no records) | Non-Lead |
| SV STEW 72 | 72 Steward Rd. | Non-Lead - Copper | | 3/4 | Installation record | Non-Lead - Copper | | 3/4 | Field inspection only (no records) | Non-Lead |
| SV EAGD 35 | 35 Eagle Dr. | Non-Lead - Copper | 6/9/2011 | 1 | Installation record | Non-Lead - Other | 6/9/2011 | 1 | Installed after 1989 -AK lead ban | Non-Lead |
| SV THOM 29/31 | 29 Thompson Cir. | Non-Lead - Copper | | 3/4 | Installation record | Non-Lead - Other | | 3/4 | Field inspection only (no records) | #N/A |
| SV THOM 32 | 32 Thompson Cir. | Non-Lead - Copper | | 3/4 | Installation record | Non-Lead - Other | | 3/4 | Field inspection only (no records) | Non-Lead |

| SV THOM 38 | 38 Thompson Cir. | Non-Lead - Copper | 11/24/1993 | 3/4 | Installation record | Non-Lead - Other | 11/24/1993 | 3/4 | Installed after 1989 -AK lead ban | Non-Lead |
|---------------------|-----------------------|----------------------|------------|-----|---|----------------------|------------|-----|---|----------|
| SV EAGD 30 | 30 Eagle Dr. | Non-Lead - Copper | | | Installation record | Non-Lead - HDPE | | | Installation record | Non-Lead |
| SV EAGD 53 | 53 Eagle Dr. | Non-Lead - Copper | | | Installation record | Non-Lead - HDPE | | | Installation record | Non-Lead |
| SV EAGC 12 | 12 Eagle Crest Ct. | Non-Lead - Copper | | | Interpolation/ statistical analysis | Non-Lead - Other | | | Interpolation/ statistical analysis | Non-Lead |
| SV EAGC 24/28 | 24 Eagle Crest Ct. | Non-Lead - Copper | | | Interpolation/ statistical analysis | Non-Lead - Other | | | Interpolation/ statistical analysis | Non-Lead |
| SV EAGC 58 | 58 Eagle Crest Ct. | Non-Lead - Copper | | | Interpolation/ statistical analysis | Non-Lead - Other | | | Interpolation/ statistical analysis | Non-Lead |
| SV EAGC 19/21/47 | 19 Eagle Crest Ct. | Non-Lead - Copper | | 1 | Installation record | Non-Lead - HDPE | | 1 | Installation record | Non-Lead |
| SV EAGD 71 | 71 Eagle Dr. | Non-Lead - Copper | | | Other - describe in notes | Non-Lead - Other | | | Interpolation/ statistical analysis | Non-Lead |
| SV EAGD 91 | 91 Eagle Dr. | Non-Lead - Copper | | | Other - describe in notes | Non-Lead - Other | | | Installed after 1989 -AK lead ban | Non-Lead |
| SV EAGD 107 | 107 Eagle Dr. | Non-Lead - Copper | | 3/4 | Installation record | Non-Lead - Copper | | 3/4 | Field inspection only (no records) | Non-Lead |
| SV EAGD 118 | 118 Eagle Dr. | Non-Lead - Copper | | 1 | Installation record | Non-Lead - Copper | | 1 | Installation record | Non-Lead |
| STUB EAGD 138 | 138 Eagle Dr. | Non-Lead - Copper | | | Installation record | N/A | | | N/A | Non-Lead |
| SV EAGD 129 | 129 Eagle Dr. | Non-Lead - Copper | | | Installation record | Non-Lead - HDPE | | | Repair / replacement record | Non-Lead |

| SV EAGD 147/149 | 147 Eagle Dr. | Non-Lead - Copper | | | Installation record | Non-Lead - Copper | | | Installation record | Non-Lead |
|--------------------|---------------|----------------------|------------|-----|---|-----------------------|------------|-----|--|----------|
| SV EAGD 181/183 | 181 Eagle Dr. | Non-Lead - Copper | 11/29/1990 | 1 | Installation record | Non-Lead - PVC | 11/29/1990 | 1 | Installation record | Non-Lead |
| SV EAGD 168 | 168 Eagle Dr. | Non-Lead - Copper | 4/5/1989 | 3/4 | Installation record | Non-Lead - Copper | 4/5/1989 | 3/4 | Repair / replacement record | Non-Lead |
| SV EAGD 240 | 240 Eagle Dr. | Non-Lead - Copper | | 1 | Repair / replacement record | Non-Lead - Plastic | | 1 | Repair / replacement record | #N/A |
| SV EAGD 264 | 264 Eagle Dr. | Non-Lead - Other | | | Installed after 1989 -AK lead ban | Non-Lead - Other | | | Installed after 1989 -AK lead ban | Non-Lead |
| SV EAGD 312 | 312 Eagle Dr. | Non-Lead - Copper | | | Installation record | Non-Lead - Copper | | | Installation record | Non-Lead |
| SV AER 37 | 37 Aerie Dr. | Non-Lead - Other | 0/0/91 | 1 | Installed after 1989 -AK lead ban | Non-Lead - Other | 0/0/91 | 1 | Installed after 1989 -AK lead ban | Non-Lead |
| SV AER 90/102 | 90 Aerie Dr. | Non-Lead - Copper | | 3/4 | Installation record | Non-Lead - Copper | | 3/4 | Installation record | Non-Lead |
| SV AER 71/99 | 71 Aerie Dr. | Non-Lead - Copper | | 1 | Repair / replacement record | Non-Lead - Copper | | 1 | Repair / replacement record | #N/A |
| SV AER 126 | 126 Aerie Dr. | Non-Lead - Copper | 7/8/1991 | 1 | Installation record | Non-Lead - Other | 7/8/1991 | 1 | Installed after 1989 -AK lead ban | Non-Lead |
| SV AER 133 | 133 Aerie Dr. | Non-Lead - Copper | | 3/4 | Installation record | Non-Lead - Copper | | 3/4 | Field inspection only (no records) | Non-Lead |
| SV AER 146 | 146 Aerie Dr. | Non-Lead - Copper | | 1 | Installation record | Non-Lead - Copper | | 1 | Field inspection only (no records) | Non-Lead |
| SV AER 181 | 181 Aerie Dr. | Non-Lead - Copper | 10/1/1990 | | Repair / replacement record | Non-Lead - HDPE | 10/1/1990 | | Installation record | Non-Lead |

| SV AER 174 | 174 Aerie Dr. | Non-Lead - Copper | 2/16/1994 | 3/4 | Installation record | Non-Lead - Other | 2/16/1994 | 3/4 | Installed after 1989 -AK lead ban | Non-Lead |
|--------------------------------|----------------------------|----------------------|-----------|-----|-----------------------------------|----------------------|-----------|-----|--|----------|
| STUB BRDE 969 | 969 East Broadway Ave. | Non-Lead - Copper | 8/1/1996 | 3/4 | Installation record | N/A | | | N/A | Non-Lead |
| STUB BRDE 941 | 941 East Broadwaay Ave. | Non-Lead - Copper | 8/1/1996 | 3/4 | Installation record | N/A | | | N/A | Non-Lead |
| SV BRDE 877 | 877 East Broadway Ave. | Non-Lead - Copper | 8/1/1996 | 3/4 | Installation record | Non-Lead - Other | 8/1/1996 | 3/4 | Installed after 1989 -AK lead ban | Non-Lead |
| SV BRDE 837/839 | 837 East Broadway Ave. | Non-Lead - Copper | | 1 | Installation record | Non-Lead - Copper | | 1 | Installation record | Non-Lead |
| SV BRDE 827 | 827 East Broadway Ave. | Non-Lead - Copper | | | Repair / replacement record | Non-Lead - Copper | | | Repair / replacement record | Non-Lead |
| SV BRDE 817 | 817 East Broadway Ave. | Non-Lead - Copper | | 3/4 | Installation record | Non-Lead - Other | 0/0/2010 | 3/4 | Installation record | #N/A |
| SV BRDE 793/799/803/8 07 | 793 East Broadway Ave. | Non-Lead - Copper | 9/5/1996 | 2 | Installation record | Non-Lead - Other | 9/5/1996 | 2 | Installed after 1989 -AK lead ban | #N/A |
| STUB BRDE 741 | 741 East Broadway Ave. | Non-Lead - Copper | 9/7/1996 | 3/4 | Installation record | N/A | | | N/A | Non-Lead |
| SV BRDE 749 | 749 East Broadway Ave. | Non-Lead - Copper | 9/7/1996 | 3/4 | Installation record | Non-Lead - Other | 9/7/1996 | 3/4 | Installed after 1989 -AK lead ban | Non-Lead |
| SV BRDE 717 | 717 East Broadway Ave. | Non-Lead - Copper | | | Installation record | Non-Lead - Copper | | | Field inspection only (no records) | Non-Lead |
| SV LOOP 173 | 173 Loop Rd. | Non-Lead - Copper | | | Repair / replacement record | Non-Lead - Copper | | | Field inspection only (no records) | Non-Lead |
| SV LOOP 160 | 160 Loop Rd. | Non-Lead - Copper | | 1 | Repair / replacement record | Non-Lead - HDPE | | 1 | Repair / replacement record | Non-Lead |

| SVLOOP 162 | 162 Loop Rd. | Non-Lead - Copper | 6/30/1994 | 3/4 | Installation record | Non-Lead - Copper | | 3/4 | Other - describe in notes | #N/A |
|------------------------|---------------------|----------------------|------------|-------|------------------------|----------------------|------------|-------|---|----------|
| SVLOOP 137 | 137 Loop Rd. | Non-Lead - Copper | | 1 | Installation record | Non-Lead - Copper | | 1 | Installation record | Non-Lead |
| SVLOOP 132 | 132 Loop Rd. | | | | | | | | | Non-Lead |
| SV LOOP 118 | 118 Loop Rd. | Non-Lead - Copper | | 3/4 | Installation record | Non-Lead - HDPE | | 3/4 | Installation record | Non-Lead |
| SV LOOP 104 | 104 Loop Rd. | Non-Lead - Copper | 11/8/1994 | 3/4 | Installation record | Non-Lead - Other | 11/8/1994 | 3/4 | Installed after 1989 -AK lead ban | Non-Lead |
| SV LOOP 88 | 88 Loop Rd. | Non-Lead - Copper | | | Installation record | Non-Lead - Copper | | | Installation record | Non-Lead |
| SVLOOP 107 | 107 Loop Rd. | Non-Lead - Copper | 12/20/2006 | 1 | Installation record | Non-Lead - HDPE | 12/20/2006 | 1 | Installation record | Non-Lead |
| SV LOOP 93 | 93 Loop Rd. | Non-Lead - Copper | 8/31/1999 | | Installation record | Non-Lead - HDPE | 8/31/1999 | | Installation record | #N/A |
| SV LOOP 40/56/60/72 | 40 Loop Rd. | Non-Lead - Copper | | | Installation record | Non-Lead - Copper | | | Installation record | Non-Lead |
| SV LOOP 63 | 63 Loop Rd. | Non-Lead - Copper | 8/1/1988 | 1 1/2 | Installation record | Non-Lead - HDPE | 8/1/1988 | 1 1/2 | Installation record | Non-Lead |
| SV PTAR 11 | 11 Ptarmigan Rd. | Non-Lead - Copper | 7/13/2006 | 3/4 | Installation record | Non-Lead - Other | 7/13/2006 | 3/4 | Installed after 1989 -AK lead ban | Non-Lead |
| SV PTAR 15 | 15 Ptarmigan Rd. | Non-Lead - Copper | 11/20/2003 | 1 | Installation record | Non-Lead - Other | 11/20/2003 | 1 | Installed after 1989 -AK lead ban | Non-Lead |
| SV PTAR 18 | 18 Ptarmigan Rd. | Non-Lead - Other | 8/26/1993 | 4 | Installation record | Non-Lead - Other | 8/26/1993 | 4 | Installation record | Non-Lead |

| SV PTAR 25 | 25 Ptarmigan Rd. | Non-Lead - Copper | 10/1/2002 | 1 | Installation record | Non-Lead - Copper | 10/1/2002 | 1 | Installation record | Non-Lead |
|--------------------|---------------------------|----------------------|------------|-----|---|-----------------------|------------|-----|---|----------|
| SV PTAR 67 | 67 Ptarmigan Rd. | Non-Lead - Copper | | | Installation record | Non-Lead - Copper | | | Installation record | Non-Lead |
| SV PTAR 87 | 87 Ptarmigan Rd. | Non-Lead - Copper | 7/9/2009 | 3/4 | Installation record | Non-Lead - Other | 7/9/2009 | 3/4 | Installed after 1989 -AK lead ban | Non-Lead |
| SV PTAR 107/109 | 107 Ptarmigan Rd. | Non-Lead - Copper | 8/29/2007 | 1 | Installation record | Non-Lead - Other | 8/29/2007 | 1 | Installed after 1989 -AK lead ban | Non-Lead |
| SV PTAR 100 | 100 Ptarmigan Rd. | Non-Lead - Copper | | | Installation record | Non-Lead - Copper | | | Other - describe in notes | Non-Lead |
| SV PTAR 129 | 129 Ptarmigan Rd. | Non-Lead - Copper | 8/26/1992 | 1 | Installation record | Non-Lead - HDPE | 8/26/1992 | 1 | Installation record | Non-Lead |
| SV DUTT 214 | 214 Dutton Rd. | Non-Lead - Other | | | Interpolation/ statistical analysis | Non-Lead - Other | | | Interpolation/ statistical analysis | Non-Lead |
| SV PTAR 415 | 415 Ptarmigan Rd. | Non-Lead - HDPE | 11/10/2000 | 1 | Repair / replacement record | Non-Lead - HDPE | 11/20/2000 | 1 | Repair / replacement record | Non-Lead |
| SV BRDE 683/701 | 683 East Broadway Ave. | Non-Lead - Copper | 7/17/1990 | 3/4 | Installation record | Non-Lead - Other | 7/17/1990 | 3/4 | Installed after 1989 -AK lead ban | Non-Lead |
| STUB BRDE 651 | 651 East Broadway Ave. | Non-Lead - Copper | 8/1/1996 | 3/4 | Installation record | N/A | | | N/A | Non-Lead |
| STUB BRDE 633 | 633 East Broadway Ave. | Non-Lead - Copper | 8/1/1996 | 3/4 | Installation record | N/A | | | N/A | Non-Lead |
| SV BRDE 599 | 599 East Broadway Ave. | Non-Lead - Copper | 9/20/1988 | 1 | Installation record | Non-Lead - Plastic | 9/20/1988 | 1 | Repair / replacement record | Non-Lead |
| SV BRDE 569 | 569 East Broadway Ave. | Non-Lead - Copper | | | Installation record | Non-Lead - Copper | | | Installation record | Non-Lead |

| STUB BRDE 533 | 533 Broadway Ave. | Non-Lead - Copper | 8/1/1996 | 3/4 | Installation record | N/A | | | N/A | Non-Lead |
|--------------------|---------------------------|----------------------|-----------|-----|------------------------|----------------------|-----------|-----|--|----------|
| SV BRDE 501 | 501 East Broadway Ave. | Non-Lead - Other | 6/8/2000 | 6 | Installation record | Non-Lead - Other | 6/8/2000 | 6 | Installation record | #N/A |
| SV DUTT 28 | 28 Dutton Rd. | Non-Lead - Copper | | 1 | Installation record | Non-Lead - Copper | | 1 | Field inspection only (no records) | #N/A |
| SV DUTT 114/116 | 114 Dutton Rd. | Non-Lead - Other | 10/1/1988 | 6 | Installation record | Non-Lead - Copper | 10/1/1988 | 2 | Installation record | #N/A |
| SV DUTT 129 | 129 Dutton Rd. | Non-Lead - Copper | 6/23/2005 | 1 | Installation record | Non-Lead - HDPE | 6/23/2005 | 1 | Installation record | Non-Lead |
| SV DUTT 137 | 137 Dutton Rd. | Non-Lead - Copper | 6/23/2005 | 1 | Installation record | Non-Lead - HDPE | 6/23/2005 | 1 | Installation record | #N/A |
| SV DUTT 130 | 130 Dutton Rd. | Non-Lead - Copper | 3/1/2000 | 1 | Installation record | Non-Lead - Copper | 3/1/2000 | | Installation record | Non-Lead |
| SV DUTT 132 | 132 Dutton Rd. | Non-Lead - Copper | 3/1/2000 | 1 | Installation record | Non-Lead - Copper | 3/1/2000 | | Installation record | Non-Lead |
| SV DUTT 171 | 171 Dutton Rd. | Non-Lead - Copper | | | Installation record | Non-Lead - Copper | | | Installation record | Non-Lead |
| SV DUTT 222 | 222 Dutton Rd. | Non-Lead - Copper | | 1 | Installation record | Non-Lead - Copper | | 1 | Installation record | Non-Lead |
| SV DUTT 250 | 250 Dutton Rd. | Non-Lead - Copper | | 1 | Installation record | Non-Lead - Copper | | 1 | Installation record | Non-Lead |
| SV DUTT 223 | 223 Dutton Rd. | Non-Lead - Copper | 9/1/2000 | | Installation record | Non-Lead - Other | 9/1/2000 | | Installed after 1989 -AK lead ban | Non-Lead |
| SVJLD 35 | 35 Jack London Dr. | Non-Lead - Copper | | 3/4 | Installation record | Non-Lead - Copper | | 3/4 | Installation record | Non-Lead |

| SVJLD 53 | 53 Jack London Dr. | Non-Lead - Copper | | | Installation record | Non-Lead - Copper | | | Installation record | Non-Lead |
|---------------|-----------------------|----------------------|----------|---|---|----------------------|----------|---|---|----------|
| SVJLD 66 | 66 Jack London Dr. | Non-Lead - Other | 9/1/2004 | | Installed after 1989 -AK lead ban | Non-Lead - Other | 9/1/2004 | | Installed after 1989 -AK lead ban | Non-Lead |
| SVJLD 71 | 71 Jack London Dr. | Non-Lead - Other | 9/1/2004 | | Installed after 1989 -AK lead ban | Non-Lead - Other | 9/1/2004 | | Installed after 1989 -AK lead ban | Non-Lead |
| SV JLD 87 | 87 Jack London Dr. | Non-Lead - Other | 9/1/2004 | | Installed after 1989 -AK lead ban | Non-Lead - Other | 9/1/2004 | | Installed after 1989 -AK lead ban | Non-Lead |
| SV DUTT 288 | 288 Dutton Rd. | Non-Lead - Copper | | | Installation record | Non-Lead - Copper | | | Installation record | Non-Lead |
| SV DUTT 312 | 312 Dutton Rd. | Non-Lead - Copper | | | Installation record | Non-Lead - Copper | | | Installation record | Non-Lead |
| STUB DUTT 340 | 340 Dutton Rd. | Non-Lead - Copper | | | Installation record | N/A | | | N/A | Non-Lead |
| SV DUTT 342 | 342 Dutton Rd. | Non-Lead - Other | 9/1/2004 | | Installed after 1989 -AK lead ban | Non-Lead - Other | 9/1/2004 | | Installed after 1989 -AK lead ban | Non-Lead |
| SV DUTT 363 | 363 Dutton Rd. | Non-Lead - Copper | 9/1/2004 | 1 | Installation record | Non-Lead - Other | 9/1/2004 | 1 | Installed after 1989 -AK lead ban | Non-Lead |
| SV DUTT 392 | 392 Dutton Rd. | Non-Lead - Copper | | 1 | Installation record | Non-Lead - Copper | | 1 | Other - describe in notes | Non-Lead |
| SV DUTT 412 | 412 Dutton Rd. | Non-Lead - Copper | 9/1/2004 | 1 | Installation record | Non-Lead - Other | 9/1/2004 | 1 | Installed after 1989 -AK lead ban | Non-Lead |
| STUB DUTT 247 | 247 Dutton Rd. | Non-Lead - Copper | 9/1/2004 | 1 | Installation record | N/A | | | N/A | #N/A |
| STUB DUTT 402 | 402 Dutton Rd. | Non-Lead - Copper | 9/1/2004 | 1 | Installation record | N/A | | | N/A | Non-Lead |

| STUB DUTT 440 | 440 Dutton Rd. | Non-Lead - Copper | 9/1/2004 | 1 | Installation record | N/A | | N/A | Non-Lead |
|--------------------|----------------|----------------------|----------|---|---|----------------------|----------|---|----------|
| SV DUTT 443/463 | 443 Dutton Rd. | Non-Lead - Other | 9/1/2004 | | Installed after 1989 -AK lead ban | Non-Lead - Other | 9/1/2004 | Installed after 1989 -AK lead ban | Non-Lead |
| SV NIRV 19 | 19 Nirvana Dr. | Non-Lead - Other | 9/1/2004 | | Installed after 1989 -AK lead ban | Non-Lead - Other | 9/1/2004 | Installed after 1989 -AK lead ban | Non-Lead |
| SV NIRV 23 | 23 Nirvana Dr. | Non-Lead - Other | 9/1/2004 | | Installed after 1989 -AK lead ban | Non-Lead - Other | 9/1/2004 | Installed after 1989 -AK lead ban | #N/A |
| SV NIRV 44 | 44 Nirvana Dr. | Non-Lead - Other | | | Interpolation/ statistical analysis | Non-Lead - Other | | Interpolation/ statistical analysis | #N/A |
| SV NIRV 46 | 46 Nirvana Dr. | Non-Lead - Other | | | Interpolation/ statistical analysis | Non-Lead - Copper | | Field inspection only (no records) | #N/A |
| SV DUTT 567 | 567 Dutton Rd. | Non-Lead - Other | 9/1/2004 | | Installed after 1989 -AK lead ban | Non-Lead - Other | 9/1/2004 | Installed after 1989 -AK lead ban | Non-Lead |
| SV DUTT 523 | 523 Dutton Rd. | Non-Lead - Other | 9/1/2004 | | Installed after 1989 -AK lead ban | Non-Lead - Other | 9/1/2004 | Installed after 1989 -AK lead ban | Non-Lead |
| SV DUTT 474 | 474 Dutton Rd. | Non-Lead - Other | 9/1/2004 | | Installed after 1989 -AK lead ban | Non-Lead - Other | 9/1/2004 | Installed after 1989 -AK lead ban | Non-Lead |
| SV DUTT 510 | 510 Dutton Rd. | Non-Lead - Copper | 9/1/2004 | | Installation record | Non-Lead - Other | 9/1/2004 | Installed after 1989 -AK lead ban | Non-Lead |
| SV DUTT 538 | 538 Dutton Rd. | Non-Lead - Copper | 9/1/2004 | | Installation record | Non-Lead - Other | 9/1/2004 | Installed after 1989 -AK lead ban | Non-Lead |
| SV DUTT 564 | 564 Dutton Rd. | Non-Lead - Copper | 9/1/2004 | | Installation record | Non-Lead - Other | 9/1/2004 | Installed after 1989 -AK lead ban | Non-Lead |
| STUB DUTT 574 | 574 Dutton Rd. | Non-Lead - Copper | 9/1/2004 | | Installation record | N/A | | N/A | Non-Lead |

| STUB DUTT 609 | 609 Dutton Rd. | Non-Lead - Copper | 9/1/2004 | | Installation record | N/A | | | N/A | Non-Lead |
|---------------|----------------|----------------------|----------|-----|---------------------|----------------------|----------|---|---|----------|
| SV DUTT 613 | 613 Dutton Rd. | Non-Lead - Copper | 9/1/2004 | | Installation record | Non-Lead - Other | 9/1/2004 | | Installed after 1989 -AK lead ban | Non-Lead |
| SV DUTT 616 | 616 Dutton Rd. | Non-Lead - Copper | 9/1/2004 | | Installation record | Non-Lead - Other | 9/1/2004 | | Installed after 1989 -AK lead ban | Non-Lead |
| SV LAKE 93 | 93 Lake Dr. | Non-Lead - Copper | | | Installation record | Non-Lead - Copper | | | Field inspection only (no records) | Non-Lead |
| SV LAKE 90 | 90 Lake Dr. | Non-Lead - Copper | | | Installation record | Non-Lead - Copper | | | Interpolation/ statistical analysis | #N/A |
| SV LAKE 78 | 78 Lake Dr. | Non-Lead - Copper | | 3/4 | Installation record | Non-Lead - Copper | | | Interpolation/ statistical analysis | #N/A |
| SV LAKE 83 | 83 Lake Dr. | Non-Lead - Copper | | | Installation record | Non-Lead - Copper | | | Interpolation/ statistical analysis | Non-Lead |
| SV LAKE 71 | 71 Lake Dr. | Non-Lead - Copper | | | Installation record | Non-Lead - Copper | | | Interpolation/ statistical analysis | Non-Lead |
| SV LAKE 68 | 68 Lake Dr. | Non-Lead - Copper | | | Installation record | Non-Lead - Copper | | | Interpolation/ statistical analysis | Non-Lead |
| SV LAKE 57 | 57 Lake Dr. | Non-Lead - Copper | | | Installation record | Non-Lead - Copper | | | Interpolation/ statistical analysis | Non-Lead |
| SV LAKE 43 | 43 Lake Dr. | Non-Lead - Copper | | | Installation record | Non-Lead - Copper | | 1 | Interpolation/ statistical analysis | Non-Lead |
| SV LAKE 48 | 48 Lake Dr. | Non-Lead - Copper | 8/1/2017 | 1 | Installation record | Non-Lead - Copper | | | Repair / replacement record | Non-Lead |
| SV LAKE 38 | 38 Lake Dr. | Non-Lead - Copper | | | Installation record | Non-Lead - Copper | | | Interpolation/ statistical analysis | Non-Lead |

| SV LAKE 20 | 20 Lake Dr. | Non-Lead - Copper | | | Installation record | Non-Lead - Copper | | | Interpolation/ statistical analysis | Non-Lead |
|----------------------------------|----------------------|----------------------|------------|-------|---|----------------------|------------|-------|---|----------|
| SV LAKE 7 | 7 Lake Dr. | Non-Lead - Copper | | | Installation record | Non-Lead - Copper | | | Interpolation/ statistical analysis | Non-Lead |
| SV LAKE 27 | 27 Lake Dr. | Non-Lead - Copper | | 3/4 | Installation record | Non-Lead - Copper | | 3/4 | Interpolation/ statistical analysis | Non-Lead |
| SV ARMS 43 | 43 ArmstrongCt. | Non-Lead - Copper | 8/31/1988 | 3/4 | Installation record | Non-Lead - Copper | | 3/4 | Interpolation/ statistical analysis | Non-Lead |
| SV ARMS 58/68/72/82/86 /92 | 58 Armstrong Ct. | Non-Lead - Copper | 9/2/1988 | 1 1/2 | Interpolation/ statistical analysis | Non-Lead - Copper | | 1 1/2 | Interpolation/ statistical analysis | Non-Lead |
| SV ARMS 77 | 77 Armstrong | Non-Lead - Copper | | | Installation record | Non-Lead - Copper | | | Interpolation/ statistical analysis | Non-Lead |
| SV GROF 16 | 16 Gromoff Ln. | Non-Lead - Copper | | | Installation record | Non-Lead - Copper | | | Interpolation/ statistical analysis | Non-Lead |
| SV GROF 38 | 38 Gromoff Ln. | Non-Lead - Copper | | | Installation record | Non-Lead - Copper | | | Interpolation/ statistical analysis | Non-Lead |
| SV BVEW 84 | 84 Bayview Ave. | Non-Lead - Copper | 8/2/1995 | 1 | Installation record | Non-Lead - Other | 8/2/1995 | 1 | Installed after 1989 -AK lead ban | Non-Lead |
| SV BVEW 50 | 50 Bayview Ave. | Non-Lead - Copper | 7/1/2004 | 3/4 | Installation record | Non-Lead - Copper | 7/1/2004 | 3/4 | Installation record | Non-Lead |
| SV ARMS 113 | 113 Armstrong Ct. | Non-Lead - Copper | 8/1/1993 | 3/4 | Installation record | Non-Lead - Other | 8/1/1993 | 3/4 | Installed after 1989 -AK lead ban | Non-Lead |
| SV ARMS 115/117 | 115 Armstrong Ct. | Non-Lead - Copper | 11/28/1997 | 3/4 | Installation record | Non-Lead - Other | 11/28/1997 | 3/4 | Installed after 1989 -AK lead ban | Non-Lead |
| SV BVEW 32 | 32 Bayview Ave. | Non-Lead - Copper | 9/16/1993 | 3/4 | Installation record | Non-Lead - Other | 9/16/1993 | 3/4 | Installed after 1989 -AK lead ban | Non-Lead |

| SV BVEW 8 | 8 Bayview Ave. | Non-Lead - Copper | 8/1/1993 | 3/4 | Installation record | Non-Lead - Other | 8/1/1993 | 3/4 | Installed after 1989 -AK lead ban | Non-Lead |
|---------------|---------------------------|----------------------|-----------|-------|-----------------------------------|----------------------|-----------|-------|--|----------|
| SV BRDE 235 | 235 East Broadway Ave. | Non-Lead - Copper | 6/19/1993 | 3/4 | Installation record | Non-Lead - Other | 6/19/1993 | 3/4 | Installed after 1989 -AK lead ban | Non-Lead |
| SV BRDE 252 | 252 East Broadway Ave. | Non-Lead - Copper | 8/27/1993 | 2 | Installation record | Non-Lead - Other | 8/27/1993 | 2 | Installed after 1989 -AK lead ban | Non-Lead |
| SV BRDE 165 | 165 East Broadway Ave. | Non-Lead - Copper | | | Installation record | Non-Lead - Copper | | | Installation record | Non-Lead |
| SV BRDE 175 | 175 East Broadway Ave. | Non-Lead - Copper | | | Installation record | Non-Lead - Copper | | | Installation record | Non-Lead |
| SV BRDE 185 | 185 East Broadway Ave. | Non-Lead - Copper | | | Installation record | Non-Lead - Copper | | | Installation record | Non-Lead |
| SV BRDE 90/96 | 90 East Broadway Ave. | Non-Lead - Copper | 8/26/1988 | 3/4 | Installation record | Non-Lead - Copper | 8/26/1988 | 3/4 | Installation record | Non-Lead |
| SV BRDE 74 | 74 East Broadway Ave. | Non-Lead - Copper | | 1 1/2 | Installation record | Non-Lead - Copper | | 1 1/2 | Installation record | Non-Lead |
| SV 6THS 50 | 50 South 6th St. | Non-Lead - Copper | 12/7/2007 | 2 | Installation record | Non-Lead - Copper | 12/7/2007 | 2 | Repair / replacement record | Non-Lead |
| SV BRDE 28 | 28 East Broadway Ave. | Non-Lead - Copper | 3/29/1994 | 1 | Installation record | Non-Lead - HDPE | 3/29/1994 | 1 | Other - describe in notes | Non-Lead |
| SV 5THS 37 | 37 South 5th St. | Non-Lead - Other | | 6 | Diameter is 3 inches or more | Non-Lead - Other | | 6 | Installation record | Non-Lead |
| SV KING 33 | 33 King St. | Non-Lead - Copper | | 3/4 | Repair / replacement record | Non-Lead - Copper | | 3/4 | Installation record | Non-Lead |
| SV KING 82/88 | 82 King St. | Non-Lead - Copper | 8/30/1988 | 1 | Installation record | Non-Lead - Other | | | Field inspection only (no records) | Non-Lead |

| SV SBAY 1156 | 1156 Summer Bay Rd. | Non-Lead - HDPE | | | Installation record | Non-Lead - HDPE | | | Installation record | Non-Lead |
|---------------|--------------------------|----------------------|-----------|-----|-----------------------------------|----------------------|-----------|-----|--|----------|
| SV KING 62/70 | 62 King St. | Non-Lead - Copper | | | Installation record | Non-Lead - Other | | | Field inspection only (no records) | Non-Lead |
| SV MISS 14 | 14 Mission Ave. | Non-Lead - Copper | 8/4/1989 | | Installation record | Non-Lead - Other | | | Other - describe in notes | Non-Lead |
| SV MISS 19/21 | 19 Mission Ave. | Non-Lead - Copper | 8/28/1996 | 1 | Installation record | Non-Lead - HDPE | 8/28/1996 | 1 | Installation record | Non-Lead |
| SV MISS 43/49 | 43 Mission Ave. | Non-Lead - Copper | 8/15/2003 | 1 | Installation record | Non-Lead - Other | 8/15/2003 | 1 | Installed after 1989 -AK lead ban | Non-Lead |
| SV BRDE 55 | 55 East Broadway Ave. | Non-Lead - Other | 5/5/1990 | 6 | Installation record | Non-Lead - Other | 5/5/1990 | 6 | Installation record | Non-Lead |
| SV BRDE 55 | 55 East Broadway Ave. | Non-Lead - Other | 6/16/1990 | 6 | Repair / replacement record | Non-Lead - Other | 6/16/1990 | 4 | Repair / replacement record | Non-Lead |
| SV BVEW 196 | 196 Bayview Ave. | Non-Lead - Copper | | 3/4 | Installation record | Non-Lead - Copper | | 3/4 | Installation record | Non-Lead |
| SV BVEW 208 | 208 Bayview Ave. | Non-Lead - Copper | | | Installation record | Non-Lead - HDPE | | | Field inspection only (no records) | Non-Lead |
| SV MISS 109 | 109 Mission Ave. | Non-Lead - Copper | | | Installation record | Non-Lead - Copper | | | Field inspection only (no records) | Non-Lead |
| SV BVEW 232 | 232 Bayview Ave. | Non-Lead - Copper | | | Repair / replacement record | Non-Lead - Copper | | | Field inspection only (no records) | Non-Lead |
| SV BVEW 242 | 242 Bayview Ave. | Non-Lead - Copper | | 1 | Repair / replacement record | Non-Lead - HDPE | | 1 | Repair / replacement record | Non-Lead |
| SV 5THN 5 | 5 North 5th St. | Non-Lead - Copper | | | Installation record | Non-Lead - Copper | | | Installation record | Non-Lead |

| SV BRDW 10 | 10 West Broadway Ave. | Non-Lead - Copper | 8/1/1988 | 3/4 | Installation record | Non-Lead - Copper | Installation record | Non-Lead |
|------------------|---------------------------|----------------------|-----------|-----|---|----------------------|--|------------|
| SV BRDW 45 | 45 West Broadway Ave. | Non-Lead - Copper | 4/8/1988 | 3/4 | Installation record | Non-Lead - Copper | Repair / replacemen record | Non-Lead |
| SV BRDW 59 | 59 West Broadway Ave. | Non-Lead - Copper | 9/22/1988 | 3/4 | Installation record | Non-Lead - Copper | Field inspection only (no records) | Non-Lead |
| SV BRDW 61 | 61 West Broadway Ave. | Non-Lead - Copper | 9/6/1988 | 3/4 | Interpolation/ statistical analysis | Non-Lead - Copper | Other - descri | Non-Lead |
| SV BRDW 77 | 77 West Broadway Ave. | Non-Lead - Copper | 9/22/1988 | 1 | Installation record | Non-Lead - Copper | Interpolation statistical analysis | / Non-Lead |
| SV BRDW 87 | 87 West Broadway Ave. | Non-Lead - Copper | 9/8/1988 | 3/4 | Installation record | Non-Lead - Copper | Interpolation statistical analysis | Non-Lead |
| SV BRDW 88 | 88 West Broadway Ave. | Non-Lead - Copper | 9/6/1988 | 3/4 | Installation record | Non-Lead - Copper | Interpolation statistical analysis | Non-Lead |
| SV BRDW 92 | 92 West Broadway Ave. | Non-Lead - Copper | 9/8/1988 | 3/4 | Installation record | Non-Lead - Copper | Interpolation statistical analysis | / Non-Lead |
| SV BRDW 95 | 95 West Broadway Ave. | Non-Lead - Copper | 9/8/1988 | 3/4 | Installation record | Non-Lead - Copper | Installation record | Non-Lead |
| SV BEDW 104 | 104 West Broadway Ave. | Non-Lead - Copper | 10/1/1994 | 3/4 | Installation record | Non-Lead - Other | Installed afte 1989 -AK lea ban | |
| STUB BRDW 105 | 105 West Broadway Ave. | Non-Lead - Copper | 10/1/1994 | 3/4 | Installation record | N/A | N/A | Non-Lead |
| SV BRDW 115 | 115 West Broadway Ave. | Non-Lead - Copper | 9/8/1988 | 3/4 | Installation record | Non-Lead - Copper | Repair / replacemen record | Non-Lead |
| STUB 3RDS 15 | 15 South 3rd St. | Non-Lead - Copper | 9/10/1988 | 3/4 | Installation record | N/A | N/A | Non-Lead |

| SV BRDW 137 | 137 West Broadway Ave. | Non-Lead - Copper | 5/18/1990 | 3/4 | Installation record | Non-Lead - HDPE | | Other - describe in notes | Non-Lead |
|------------------|---------------------------|----------------------|------------|-----|---|----------------------|-----|---|----------|
| SV BRDW 136 | 136 West Broadway Ave. | Non-Lead - Copper | 9/10/1988 | 3/4 | Installation record | Non-Lead - Copper | | Other - describe in notes | Non-Lead |
| SV BRDW 144 | 144 West Broadway Ave. | Non-Lead - Copper | 9/10/1988 | 3/4 | Installation record | Non-Lead - Copper | | Installation record | #N/A |
| SV BRDW 149 | 149 West Broadway Ave. | Non-Lead - Copper | | 3/4 | Repair / replacement record | Non-Lead - Copper | 3/4 | Repair / replacement record | Non-Lead |
| SV BRDW 156 | 156 West Broadway Ave. | Non-Lead - Copper | 9/15/1994 | 3/4 | Installation record | Non-Lead - Other | | Installed after 1989 -AK lead ban | #N/A |
| SV BRDW 161 | 161 West Broadway Ave. | Non-Lead - Copper | 9/29/1988 | 3/4 | Installation record | Non-Lead - HDPE | | Field inspection only (no records) | Non-Lead |
| SV BRDW 166 | 166 West Broadway Ave. | Non-Lead - Copper | 9/10/1988 | 3/4 | Installation record | Non-Lead - Other | | Interpolation/ statistical analysis | Non-Lead |
| SV BRDW 174 | 174 West Broadway Ave. | Non-Lead - Copper | | | Interpolation/ statistical analysis | Non-Lead - Other | | Interpolation/ statistical analysis | Non-Lead |
| SV BRDW 188 | 188 West Broadway Ave. | Non-Lead - Copper | | 1 | Installation record | Non-Lead - Copper | | Installation record | Non-Lead |
| STUB BRDW 194 | 194 West Broadway Ave. | Non-Lead - Copper | 10/1/1994 | 3/4 | Installation record | N/A | | N/A | Non-Lead |
| STUB BRDW 191 | 191 West Broadway Ave. | Non-Lead - Copper | 10/1/1994 | 3/4 | Installation record | N/A | | N/A | Non-Lead |
| SV BRDW 204 | 204 West Broadway Ave. | Non-Lead - Copper | 10/28/2007 | 1 | Installation record | Non-Lead - Other | | Installed after 1989 -AK lead ban | Non-Lead |
| SV BRDW 201 | 201 West Broadway Ave. | Non-Lead - Copper | 9/11/1988 | 1 | Installation record | Non-Lead - Copper | | Installation record | Non-Lead |

| SV BRDW 215 | 215 West Broadway Ave. | Non-Lead - Copper | 9/10/1988 | 3/4 | Installation record | Non-Lead - Other | | Field inspection only (no records) | Non-Lead |
|--------------------|---------------------------|----------------------|------------|-----|---|-----------------------|-------|---|----------|
| STUB BRDW 216 | 216 West Broadway Ave. | Non-Lead - Copper | 10/16/2007 | 3/4 | Repair / replacement record | N/A | | N/A | #N/A |
| SV BRDW 226 | 226 West Broadway Ave. | Non-Lead - Copper | 9/11/1988 | 3/4 | Installation record | Non-Lead - Other | | Field inspection only (no records) | #N/A |
| SV BRDW 243 | 243 West Broadway Ave. | Non-Lead - Copper | 9/10/1988 | 3/4 | Repair / replacement record | Non-Lead - Copper | | Installation record | Non-Lead |
| SV BRDW 265 | 265 West Broadway Ave. | Non-Lead - Other | | 4 | Installation record | Non-Lead - Other | | Diameter is 3 inches or more | Non-Lead |
| SV BRDW 321 | 321 West Broadway Ave. | Non-Lead - Copper | | 2 | Installation record | Non-Lead - Copper | | Installation record | Non-Lead |
| SV BRDW 265 (2) | 265 West Broadway Ave. | Non-Lead - Copper | 2/18/2021 | 2 | Installation record | Non-Lead - Copper | 1 1/2 | Installation record | #N/A |
| SV BRDW 347 | 347 West Broadway Ave. | Non-Lead - Copper | | | Installed after 1989 -AK lead ban | Non-Lead - Other | | Installed after 1989 -AK lead ban | Non-Lead |
| SV CYRI 26 | 26 Cyri Cir. | Non-Lead - Copper | 12/22/1989 | 3/4 | Installation record | Non-Lead - HDPE | | Field inspection only (no records) | Non-Lead |
| STUB BRDW 35 | 35 West Broadway Ave. | Non-Lead - Copper | 9/7/1988 | 3/4 | Installation record | N/A | | N/A | Non-Lead |
| SV CYRI 21 | 21 Cyri Cir. | Non-Lead - Copper | 9/7/1988 | 3/4 | Installation record | Non-Lead - Plastic | 3/4 | Interpolation/ statistical analysis | Non-Lead |
| SV CYRI 31 | 31 Cyri Cir. | Non-Lead - Copper | 9/7/1988 | 3/4 | Installation record | Non-Lead - Plastic | | Interpolation/ statistical analysis | Non-Lead |
| SV CYRI 35 | 35 Cyri Cir. | Non-Lead - Copper | 9/7/1988 | 3/4 | Installation record | Non-Lead - Plastic | | Interpolation/ statistical analysis | Non-Lead |

| SV CYRI 36 | 36 Cyri Cir. | Non-Lead - Copper | 9/7/1988 | 3/4 | Installation record | Non-Lead - Plastic | | Interpolation/ statistical analysis | Non-Lead |
|---------------|----------------------|----------------------|-----------|-----|-----------------------------------|-----------------------|---|---|----------|
| SV CYRI 38 | 38 Cyri Cir. | Non-Lead - Copper | 9/7/1988 | 3/4 | Installation record | Non-Lead - Plastic | | Field inspection only (no records) | #N/A |
| SV 4THN 22 | 22 North 4th St. | Non-Lead - Copper | 9/22/1988 | 3/4 | Installation record | Non-Lead - Copper | | Installation record | #N/A |
| SV 4THN 17 | 17 North 4th St. | Non-Lead - Copper | 9/23/1988 | 3/4 | Installation record | Non-Lead - Plastic | | Installation record | #N/A |
| SV 4THN 29 | 29 North 4th St. | Non-Lead - Copper | 9/23/1988 | 3/4 | Installation record | Non-Lead - Copper | | Installation record | #N/A |
| SV 3RDS 26 | 26 South 3rd St. | Non-Lead - Copper | | | Installation record | Non-Lead - Other | | Field inspection only (no records) | #N/A |
| SV 3RDS 37 | 37 South 3rd St. | Non-Lead - Copper | | 3/4 | Installation record | Non-Lead - Copper | | Installation record | #N/A |
| SV 3RDS 43 | 43 South 3rd St. | Non-Lead - Copper | 8/1/1994 | 3/4 | Installation record | Non-Lead - Other | | Installed after 1989 -AK lead ban | Non-Lead |
| SV 3RDS 57 | 57 South 3rd St. | Non-Lead - Copper | 5/22/1990 | 1 | Installation record | Non-Lead - Plastic | | Repair / replacement record | #N/A |
| SV 3RDS 60 | 60 South 3rd St. | Non-Lead - Copper | | 3/4 | Installation record | Non-Lead - Copper | | Installation record | Non-Lead |
| SV RIVR 107 | 107 Riverside Dr. | Non-Lead - Copper | 4/21/1990 | 1 | Installation record | Non-Lead - Other | | Installed after 1989 -AK lead ban | Non-Lead |
| SV RIVR 77/81 | 77 Riverside Dr. | Non-Lead - Copper | | 3/4 | Repair / replacement record | | | | Non-Lead |
| SV RIVR 87 | 87 Riverside Dr. | Non-Lead - Copper | 9/1/1988 | 1 | Installation record | Non-Lead - HDPE | 1 | Repair / replacement record | Non-Lead |

| SV RIVR 149 | 149 Riverside Dr. | Non-Lead - Copper | 9/14/1988 | | Installation record | Non-Lead - Copper | | Repair / replacement record | #N/A |
|---------------------|----------------------|----------------------|------------|-----|---|----------------------|---|---|----------|
| SV RIVR 159 | 159 Riverside Dr. | Non-Lead - Copper | | 3/4 | Installation record | Non-Lead - HDPE | | Other - describe in notes | Non-Lead |
| SV RIVR 177 | 177 Riverside Dr. | Non-Lead - Copper | 9/19/1988 | | Installation record | Non-Lead - Other | | Repair / replacement record | Non-Lead |
| SV 4THS 30 | 30 South 4th St. | Non-Lead - Copper | 4/7/1990 | 1 | Installation record | Non-Lead - Copper | | Installation record | #N/A |
| SV 4THS 31/45/59 | 31 South 4th St. | Non-Lead - Other | 10/22/1990 | 2 | Installation record | Non-Lead - Copper | 2 | Installation record | Non-Lead |
| SVALUT6 | 6 Aleutian Ave. | Non-Lead - Copper | | 3/4 | Interpolation/ statistical analysis | Non-Lead - Copper | | Interpolation/ statistical analysis | Non-Lead |
| SV ALUT 13/15 | 13 Aleutian Ave. | Non-Lead - Copper | | 1 | Repair / replacement record | Non-Lead - Copper | 1 | Repair / replacement record | Non-Lead |
| STUB ALUT 18 | 18 Aleutian Ave. | Non-Lead - Copper | | 3/4 | Interpolation/ statistical analysis | N/A | | N/A | Non-Lead |
| SVALUT 20 | 20 Aleutian Ave. | Non-Lead - Copper | 9/27/1993 | 3/4 | Installation record | Non-Lead - Copper | | Installation record | Non-Lead |
| SVALUT 22 | 22 Aleutian Ave. | Non-Lead - Copper | | 3/4 | Installation record | Non-Lead - Copper | | Installation record | Non-Lead |
| SVALUT33 | 33 Aleutian Ave. | Non-Lead - Copper | | 3/4 | Installation record | Non-Lead - Copper | | Installation record | Non-Lead |
| STUB 2NDS 27 | 27 South 2nd St. | Non-Lead - Copper | 11/22/1989 | 3/4 | Installation record | N/A | | N/A | Non-Lead |
| STUB ALUT 48 | 48 Aleutian Ave. | Non-Lead - Copper | | 3/4 | Installation record | N/A | | N/A | #N/A |

| SVALUT52 | 52 Aleutian Ave. | Non-Lead - Copper | | | Installation record | Non-Lead - HDPE | Repair / replacement record | Non-Lead |
|--------------|---------------------|----------------------|-----------|-----|-----------------------------------|----------------------|---|----------|
| SV ALUT 66 | 66 Aleutian Ave. | Non-Lead - Copper | | 3/4 | Installation record | Non-Lead - Copper | Installation record | Non-Lead |
| SVALUT 68 | 68 Aleutian Ave. | Non-Lead - Copper | 5/19/2015 | 3/4 | Installation record | Non-Lead - Other | Installed after 1989 -AK lead ban | Non-Lead |
| SVALUT 71 | 71 Aleutian Ave. | Non-Lead - Copper | 4/18/2014 | 3/4 | Installation record | Non-Lead - Other | Installed after 1989 -AK lead ban | #N/A |
| SVALUT 76 | 76 Aleutian Ave. | Non-Lead - Copper | 4/10/1989 | 1 | Installation record | Non-Lead - Other | Interpolation/ statistical analysis | #N/A |
| SV RIVR 85 | 85 Riversidr Dr. | Non-Lead - Copper | | 1 | Installation record | Non-Lead - HDPE | Repair / replacement record | Non-Lead |
| SV 2NDN 11 | 11 North 2nd St. | Non-Lead - Copper | | 3/4 | Installation record | Non-Lead - Copper | Other - describe in notes | Non-Lead |
| STUB 2NDN 14 | 14 North 2nd St. | Non-Lead - Copper | | | Installation record | N/A | N/A | Non-Lead |
| STUB 2NDN 23 | 23 North 2nd St. | Non-Lead - Copper | | | Installation record | N/A | N/A | Non-Lead |
| SV 2NDN 28 | 28 North 2nd St. | Non-Lead - Copper | 9/14/1988 | 1 | Repair / replacement record | Non-Lead - Copper | Installation record | Non-Lead |
| SV BVEW 176 | 176 Bayview Ave. | Non-Lead - Copper | | | Repair / replacement record | Non-Lead - HDPE | Repair / replacement record | Non-Lead |
| SV BVEW 308 | 308 Bayview Ave. | Non-Lead - Copper | | | Installation record | Non-Lead - HDPE | Field inspection only (no records) | Non-Lead |
| SV BVEW 316 | 316 Bayview Ave. | Non-Lead - Copper | | | Installation record | Non-Lead - HDPE | Field inspection only (no records) | #N/A |

| SV BVEW 356 | 356 Bayview Ave. | Non-Lead - Copper | | | Installation record | Non-Lead - Copper | | Installation record | #N/A |
|------------------|-----------------------|----------------------|-----------|-----|--|----------------------|-----|--|--|
| SV BVEW 340 | 340 Bayview Ave. | Non-Lead - Copper | | | Installation record | Non-Lead - Copper | | Installation record | Non-Lead |
| SV BVEW 372 | 372 Bayview Ave. | Non-Lead - Copper | | 1 | Installation record | Non-Lead - Copper | 1 | Installation record | Non-Lead |
| SV BVEW 390 | 390 Bayview Ave. | Non-Lead - Copper | | 3/4 | Installation record | Galvanized | | Field inspection only (no records) | Non-Lead |
| SV BVEW 402 | 402 Bayview Ave. | Non-Lead - Copper | | 3/4 | Installation record | Non-Lead - Copper | | Field inspection only (no records) | Non-Lead |
| SV BVEW 414 | 414 Bayview Ave. | Non-Lead - Copper | | 1 | Installation record | Non-Lead - HDPE | 1 | Installation record | Non-Lead |
| SV BVEW 426 | 426 Bayview Ave. | Non-Lead - Copper | | | Field inspection only (no records) | Non-Lead - HDPE | | Field inspection only (no records) | Non-Lead |
| STUB BVEW 452 | 452 Bayview Ave. | Non-Lead - Copper | 9/14/1988 | 1 | Installation record | N/A | | N/A | Non-Lead |
| SV BVEW 456 | 456 Bayveiw Ave. | Non-Lead - Copper | 9/15/1988 | 3/4 | Installation record | Non-Lead - HDPE | | Field inspection only (no records) | Galvanized- Requiring- Replacement |
| SV BVEW 466 | 466 Bayview Ave. | Non-Lead - Copper | 9/15/1988 | 1 | Installation record | Non-Lead - Copper | | Field inspection only (no records) | Non-Lead |
| SV BFOX 111 | 111 Blue Fox Alley | Non-Lead - Copper | 9/15/1988 | 3/4 | Installation record | Non-Lead - Copper | 3/4 | Installation record | Non-Lead |
| SV BFOX 113 | 113 Blue Fox Alley | Non-Lead - Copper | 9/15/1988 | 3/4 | Installation record | Non-Lead - Copper | 3/4 | Installation record | Non-Lead |
| SV BVEW 470 | 470 Bayview Ave. | Non-Lead - Copper | 8/1/1994 | 3/4 | Installation record | Non-Lead - Other | | Installed after 1989 -AK lead ban | #N/A |

| SV BVEW 478 | 478 Bayview Ave. | Non-Lead - Copper | | | Repair / replacement record | Non-Lead - Other | | Repair / replacement record | Non-Lead |
|---------------|-----------------------------|----------------------|-----------|-------|---|-----------------------|--|---|----------|
| SV BVEW 486 | 486 Bayview Ave. | Non-Lead - Copper | 9/1/1991 | 3/4 | Installed after 1989 -AK lead ban | Non-Lead - Other | | Installed after 1989 -AK lead ban | Non-Lead |
| SV BVEW 494 | 494 Bayview Ave. | Non-Lead - Copper | | 3/4 | Repair / replacement record | Non-Lead - Copper | | Other - describe in notes | Non-Lead |
| SV BVEW 498 | 498 Bayview Ave. | Non-Lead - Copper | 8/1/1994 | 3/4 | Installation record | Non-Lead - Other | | Installed after 1989 -AK lead ban | Non-Lead |
| SV BRDW 404 B | 404 B West Broadway Ave. | Non-Lead - Copper | 9/21/1988 | 1 | Repair / replacement record | Non-Lead - Plastic | | Repair / replacement record | Non-Lead |
| SV BRDW 404 A | 404 A West Broadway Ave. | Non-Lead - Copper | | 2 | Installation record | Non-Lead - Copper | | Repair / replacement record | Non-Lead |
| SV BRDW 406 | 406 West Broadway Ave. | Non-Lead - Copper | | 1 1/2 | Installation record | Non-Lead - Copper | | Installation record | Non-Lead |
| SV BRDW 406 F | 406 F West Broadway Ave. | Non-Lead - Other | | 6 | Installation record | Non-Lead - Other | | Diameter is 3 inches or more | Non-Lead |
| SV BRDW 675 | 675 West Broadway Ave. | Non-Lead - Copper | 10/1/1988 | 2 | Installation record | Non-Lead - Copper | | Repair / replacement record | Non-Lead |
| SV BRDW 436 | 436 West Broadway Ave. | Non-Lead - Copper | | 1 1/2 | Installation record | Non-Lead - Copper | | Installation record | #N/A |
| STUB FRNK 17 | 17 Franks Alley | Non-Lead - Copper | | 3/4 | Installation record | N/A | | N/A | Non-Lead |
| SV FRNK 19 | 19 Franks Alley | Non-Lead - Copper | 9/21/1988 | 3/4 | Installation record | Non-Lead - HDPE | | Repair / replacement record | Non-Lead |
| SV BRDW 452 | 452 West Broadway Ave. | Non-Lead - Copper | 9/21/1988 | 1 1/2 | Installation record | Non-Lead - Copper | | Installation record | Non-Lead |

| SV BRDW 551 (600) | 551 (600) West Broadway Ave. | Non-Lead - Copper | 10/1/1988 | 1 1/2 | Installation record | Non-Lead - Copper | | Field inspection only (no records) | Non-Lead |
|----------------------|---------------------------------|----------------------|-----------|-------|-----------------------------------|----------------------|-----|--|----------|
| SV ELNR 64 | 64 Eleanor Dr. | Non-Lead - Other | 12/1/1998 | 6 | Installation record | Non-Lead - Other | | Diameter is 3 inches or more | Non-Lead |
| SV ELNR 79 | 79 Eleanor Dr. | Non-Lead - Other | 8/12/1995 | 4 | Installation record | Non-Lead - Copper | | Installation record | #N/A |
| STUB ABR 74 | 74 Airport Beach Rd. | Non-Lead - Copper | 8/16/1990 | 3/4 | Installation record | N/A | | N/A | Non-Lead |
| SV ABR 82 | 82 Airport Beach Rd. | Non-Lead - Copper | | | Installation record | Non-Lead - Copper | | Installation record | Non-Lead |
| SV HAY 34 | 34 Haystack Dr. | Non-Lead - Copper | 8/1/1988 | 1 | Installation record | Non-Lead - HDPE | | Installation record | Non-Lead |
| SV HAY 50 | 50 Haystack Dr. | Non-Lead - Copper | | 1 | Installation record | Non-Lead - Copper | | Installation record | Non-Lead |
| SV HAY 64/66 | 64 Haystack Dr. | Non-Lead - Copper | 5/31/1990 | 1 | Installation record | Non-Lead - Other | | Installed after 1989 -AK lead ban | Non-Lead |
| SV HAY 78/80 | 78 Haystack Dr. | Non-Lead - Copper | 6/1/1990 | 1 | Installation record | Non-Lead - Other | | Installed after 1989 -AK lead ban | #N/A |
| SV HAY 90 | 90 Haystack Dr. | Non-Lead - Copper | 6/23/1992 | 3/4 | Installation record | Non-Lead - Other | | Installed after 1989 -AK lead ban | Non-Lead |
| SV HAY 102 | 102 Haystack Dr. | Non-Lead - Copper | 8/1/1988 | 3/4 | Installation record | Non-Lead - Copper | 3/4 | Installation record | Non-Lead |
| SV HAY 366 | 366 Haystack Dr. | Non-Lead - Copper | | 3/4 | Repair / replacement record | Non-Lead - HDPE | | Installation record | Non-Lead |
| SV HAYL 54 | 54 Lower Haystack Dr. | Non-Lead - Copper | | 1 | Repair / replacement record | Non-Lead - Copper | | Field inspection only (no records) | Non-Lead |

| SV HAY 427 | 427 Haystack Dr. | Non-Lead - Copper | | 3/4 | Installation record | Non-Lead - Other | Field inspection only (no records) | Non-Lead |
|-------------------|---------------------------|----------------------|-----------|-----|---|----------------------|---|----------|
| SV HAYL 107 | 107 Lower Haystack Dr. | Non-Lead - Copper | | 3/4 | Installation record | Non-Lead - Copper | Other - describe in notes | Non-Lead |
| SV HAY 447/449 | 447 Haystack Dr. | Non-Lead - Copper | 9/22/1998 | 3/4 | Installation record | Non-Lead - Other | Field inspection only (no records) | Non-Lead |
| SV HAY 469 | 469 Haystack Dr. | Non-Lead - Copper | 7/1/1989 | | Repair / replacement record | Non-Lead - HDPE | Field inspection only (no records) | Non-Lead |
| SV HAYL 111 | 111 Lower Haystack Dr. | Non-Lead - Copper | 9/26/2003 | 1 | Installation record | Non-Lead - Other | Installed after 1989 -AK lead ban | Non-Lead |
| SV HAY 487 | 487 Haystack Dr. | Non-Lead - Copper | | 3/4 | Installation record | Non-Lead - Other | Interpolation/ statistical analysis | Non-Lead |
| SV HAY 502 | 502 Haystack Dr. | Non-Lead - Copper | | 3/4 | Installation record | Non-Lead - Other | Interpolation/ statistical analysis | Non-Lead |
| SV TRAP 93 | 93 Trapper Dr. | Non-Lead - Copper | | 3/4 | Installation record | Non-Lead - HDPE | Field inspection only (no records) | Non-Lead |
| SV TRAP 86 | 86 Trapper Dr. | Non-Lead - Copper | | 3/4 | Installation record | Non-Lead - HDPE | Field inspection only (no records) | Non-Lead |
| SV TRAP 120 | 120 Trapper Dr. | Non-Lead - Copper | 3/15/1989 | 3/4 | Installation record | Non-Lead - Copper | Repair / replacement record | Non-Lead |
| SV TRAP 139 | 139 Trapper Dr. | Non-Lead - Copper | | 3/4 | Installation record | Non-Lead - Other | Field inspection only (no records) | Non-Lead |
| SV TRAP 141 | 141 Trapper Dr. | Non-Lead - Other | | | Installed after 1989 -AK lead ban | Non-Lead - Other | Field inspection only (no records) | Non-Lead |
| SV TRAP 144 | 144 Trapper Dr. | Non-Lead - Copper | 4/3/2000 | 1 | Installation record | Non-Lead - Other | Installed after 1989 -AK lead ban | Non-Lead |

| SV TRAP 146/148 | 146 Trapper Dr. | Non-Lead - Copper | 10/3/2008 | 1 | Installation record | Non-Lead - Other | Installed after 1989 -AK lead ban | Non-Lead |
|--------------------|-----------------|----------------------|------------|-------|-----------------------------------|----------------------|---|----------|
| SV TRAP 189 | 189 Trapper Dr. | Non-Lead - Copper | 8/25/1998 | 3/4 | Installation record | Non-Lead - Other | Installed after 1989 -AK lead ban | Non-Lead |
| SV TRAP 187 | 187 Trapper Dr. | Non-Lead - Copper | 5/11/2023 | 3/4 | Installation record | Non-Lead - Other | Installed after 1989 -AK lead ban | Non-Lead |
| SV TRAP 361 | 361 Trapper Dr. | Non-Lead - Copper | 9/28/1998 | 1 1/2 | Installation record | Non-Lead - HDPE | Installation record | Non-Lead |
| SV TRAP 204 | 204 Trapper Dr. | Non-Lead - Copper | 11/4/2008 | 1 | Installation record | Non-Lead - Other | Installed after 1989 -AK lead ban | Non-Lead |
| SV RAVN 348 | 348 Raven Way | Non-Lead - Copper | 8/26/2014 | 1 | Installation record | Non-Lead - Other | Installed after 1989 -AK lead ban | Non-Lead |
| SV RAVN 332 | 332 Raven Way | Non-Lead - Copper | | 1 | Installation record | Non-Lead - HDPE | Installation record | Non-Lead |
| SV RAVN 316 | 316 Raven Way | Non-Lead - Copper | | | Repair / replacement record | Non-Lead - Copper | Repair / replacement record | Non-Lead |
| SV RAVN 295 | 295 Raven Way | Non-Lead - Copper | | | Repair / replacement record | Non-Lead - Other | Installed after 1989 -AK lead ban | Non-Lead |
| SV RAVN 285 | 285 Raven Way | Non-Lead - Copper | | | Repair / replacement record | Non-Lead - Other | Installed after 1989 -AK lead ban | Non-Lead |
| SV RAVN 299 | 299 Raven Way | Non-Lead - Copper | 10/7/2019 | 1 | Installation record | Non-Lead - Other | Installed after 1989 -AK lead ban | Non-Lead |
| SV RAVN 273 | 273 Raven Way | Non-Lead - Copper | 10/27/1995 | 1 | Installation record | Non-Lead - HDPE | Installation record | Non-Lead |
| SV BLUF 16 | 16 Bluff Ct. | Non-Lead - Copper | 7/29/1992 | 1 | Repair / replacement record | Non-Lead - Copper | Repair / replacement record | Non-Lead |

| SV RAVN 220 | 220 Raven Way | Non-Lead - Copper | | 3/4 | Installation record | Non-Lead - Copper | | | Installation record | Non-Lead |
|--------------------|--------------------------|----------------------|------------|-----|---|----------------------|------------|---|---|----------|
| SV RAVN 134/138 | 134 Raven Way | Non-Lead - HDPE | 9/2/1998 | 3/4 | Installation record | Non-Lead - Other | | | Installed after 1989 -AK lead ban | Non-Lead |
| SV RAVN 196 | 196 Raven Way | Non-Lead - Copper | | | Installation record | Non-Lead - Copper | | | Installation record | Non-Lead |
| SV RAVN 184/188 | 184 Raven Way | Non-Lead - Copper | 5/24/2016 | | Installation record | Non-Lead - HDPE | | | Installation record | Non-Lead |
| SV RAVN 125 | 125 Raven Way | Non-Lead - Other | 11/13/2011 | 1 | Installed after 1989 -AK lead ban | Non-Lead - Other | 11/13/2011 | 1 | Installed after 1989 -AK lead ban | Non-Lead |
| SV RAVN 43 | 43 Raven Way | Non-Lead - Other | 8/10/1993 | | Installation record | Non-Lead - Other | | | Diameter is 3 inches or more | Non-Lead |
| SV LVEL 34 | 34 Levelle Ct | Non-Lead - Other | 7/16/1992 | | Installation record | Non-Lead - Other | | | Diameter is 3 inches or more | Non-Lead |
| SV ABR 310 | 310 Airport Beach Rd. | Non-Lead - Other | | | Installation record | Non-Lead - Other | | | Diameter is 3 inches or more | Non-Lead |
| SV SAFE 10 | 10 Safety Way | Non-Lead - Copper | | | Installation record | Non-Lead - Copper | | | Installation record | Non-Lead |
| SV SAFE 29 | 29 Safety Way | Non-Lead - Copper | | | Diameter is 3 inches or more | Non-Lead - Other | | | Diameter is 3 inches or more | Non-Lead |
| STUB 375/377 | 375 Airport Beach Rd. | Non-Lead - Copper | | | Installation record | N/A | | | N/A | Non-Lead |
| STUB ABR 381 | 381 Airport Beach Rd. | Non-Lead - Copper | | | Installation record | N/A | | | N/A | Non-Lead |
| STUB CAPT 31 | 31 Captains Bay Rd. | Non-Lead - Copper | | | Installation record | N/A | | | N/A | Non-Lead |

| STUB CAPT 34 | 34 Captains Bay Rd. | Non-Lead - Copper | | 3/4 | Repair / replacement record | N/A | | N/A | Non-Lead |
|---------------|---------------------------|----------------------|------------|-----|---|----------------------|--|---|----------|
| SV CAPT 1200 | 1200 Captains Bay Rd. | Non-Lead - Other | | 4 | Installation record | Non-Lead - Other | | Diameter is 3 inches or more | Non-Lead |
| SV PYR 1300 | 1300 Pyramid Creek Rd. | Non-Lead - HDPE | | | Installation record | Non-Lead - HDPE | | Installation record | #N/A |
| STUB PYR 254 | 254 Pyramid Creek Rd. | Non-Lead - Copper | | 1 | Installation record | N/A | | N/A | #N/A |
| SV PYR 66-76 | 66 Pyramid Creek Rd. | Non-Lead - Other | | 8 | Installation record | Non-Lead - Other | | Diameter is 3 inches or more | #N/A |
| SV CAPT 2173 | 2173 Captains Bay Rd. | Non-Lead - Other | | 6 | Installation record | Non-Lead - PVC | | Installation record | #N/A |
| SV HENS 105 | 105 Henry Swanson Dr. | Non-Lead - Copper | | 3/4 | Installation record | Non-Lead - Copper | | Installation record | Non-Lead |
| SV HENS 550 | 550 Henry Swanson Dr. | Non-Lead - Other | 8/1/2013 | 3 | Installation record | Non-Lead - Other | | Installation record | Non-Lead |
| SV HENS 562 | 562 Henry Swanson Dr. | Non-Lead - Other | 8/1/2013 | 3 | Installation record | Non-Lead - Other | | Installation record | #N/A |
| SV HENS 570 | 570 Henry Swanson Dr. | Non-Lead - Copper | 8/1/2013 | 1 | Installation record | Non-Lead - Other | | Installed after 1989 -AK lead ban | Non-Lead |
| STUB HENS 575 | 573 Henry Swanson Dr. | Non-Lead - Copper | 8/1/2013 | | Installation record | N/A | | N/A | Non-Lead |
| SV HENS 576 | 576 Henry Swanson Dr. | Non-Lead - Other | 8/1/2013 | 3 | Installation record | Non-Lead - Other | | Installation record | Non-Lead |
| SV ABR 1177 | 1177 Airport Beach Rd. | Non-Lead - Other | 12/10/1990 | | Installed after 1989 -AK lead ban | Non-Lead - Other | | Installed after 1989 -AK lead ban | Non-Lead |

| SV ABR 1201 | 1201 Airport Beach Rd. | Non-Lead - Other | 12/10/1990 | | Installed after 1989 -AK lead ban | Non-Lead - Other | | Installed after 1989 -AK lead ban | Non-Lead |
|----------------|---------------------------|----------------------|------------|---|---|----------------------|---|---|----------|
| STUB ABR 1246 | 1246 Airport Beach Rd. | Non-Lead - Copper | 6/30/1992 | 2 | Installation record | N/A | | N/A | Non-Lead |
| SV GIL 17 | 17 Gilman Rd. | Non-Lead - Copper | 9/27/2019 | 2 | Installation record | Non-Lead - Other | | Installed after 1989 -AK lead ban | #N/A |
| SV GIL 19 | 19 Gilman Rd. | Non-Lead - Other | 10/7/1999 | 6 | Installation record | Non-Lead - Other | 6 | Diameter is 3 inches or more | Non-Lead |
| SV GIL 42 | 42 Gilman Rd | Non-Lead - Copper | | 1 | Repair / replacement record | Non-Lead - HDPE | | Repair / replacement record | Non-Lead |
| SV GIL 80 | 80 Gilman Rd. | Non-Lead - Other | | 6 | Installation record | Non-Lead - Copper | 2 | Repair / replacement record | Non-Lead |
| SV GIL 91 | 91 Gilman Rd. | Non-Lead - Other | | 6 | Installation record | Non-Lead - Other | 6 | Diameter is 3 inches or more | #N/A |
| SV GIL 109 | 109 Gilman Rd. | Non-Lead - Copper | | 2 | Installation record | Non-Lead - HDPE | | Installation record | Non-Lead |
| STUB GIL 157 | 157 Gilman Rd. | Non-Lead - Other | | 6 | Installation record | N/A | | N/A | Non-Lead |
| SV GIL 146 | 146 Gilman Rd. | Non-Lead - Other | | 4 | Installation record | Non-Lead - Other | 4 | Diameter is 3 inches or more | Non-Lead |
| SV GIL 179 | 179 Gilman Rd. | Non-Lead - Other | | 2 | Repair / replacement record | Non-Lead - Other | | Repair / replacement record | Non-Lead |
| SV GIL 179 (2) | 179 Gilman Rd. | Non-Lead - Other | | 6 | Installation record | Non-Lead - Other | 6 | Diameter is 3 inches or more | Non-Lead |
| STUB GIL 188 | 188 Gilman Rd. | Non-Lead - Other | | 6 | Installation record | N/A | | N/A | Non-Lead |

| SV GIL 188 | 188 Gilman Rd. | Non-Lead - Other | | 6 | Installation record | Non-Lead - Other | 6 | Diameter is 3 inches or more | #N/A |
|----------------------|----------------------------|----------------------|----------|-------|--|----------------------|---|--|----------|
| SV PSW 22 | 22 Pacesetter Way | Non-Lead - Copper | 1/7/1994 | 1 1/2 | Installation record | Non-Lead - Copper | | Repair / replacement record | Non-Lead |
| SV PSWS 35 | 35 South Pacesetter Way | Non-Lead - Other | | | Installation record | Non-Lead - Other | | Diameter is 3 inches or more | Non-Lead |
| SV PSWS 75 | 75 South Pacesetter Way | Non-Lead - Other | | 6 | Installation record | Non-Lead - HDPE | | Installation record | Non-Lead |
| SV PSWS 75 (2) | 75 South Pacesetter Way | Non-Lead - Copper | | 2 | Installation record | Non-Lead - Copper | | Repair / replacement record | #N/A |
| SV PSWS 88 | 88 South Pacesetter Way | Non-Lead - Other | | | Installation record | Non-Lead - Other | | Diameter is 3 inches or more | Non-Lead |
| SV PSWN 60 | 60 North Pacesetter Way | Non-Lead - Other | | | Installation record | Non-Lead - Other | | Diameter is 3 inches or more | Non-Lead |
| SV PSWN 40 | 40 North Pacesetter Way | Non-Lead - Other | | | Installation record | Non-Lead - Other | | Diameter is 3 inches or more | Non-Lead |
| SV PSW 88 (100) | 88 Pacesetter Way | Non-Lead - Other | | | Installation record | Non-Lead - Other | | Diameter is 3 inches or more | Non-Lead |
| SV PSWN 88 (700) | 88 North Pacesetter Way | Non-Lead - Other | | | Installation record | Non-Lead - Other | | Diameter is 3 inches or more | Non-Lead |
| SV PSWN 88 (100) | 88 North Pacesetter Way | Non-Lead - Other | | | Field inspection only (no records) | Non-Lead - Other | | Field inspection only (no records) | Non-Lead |
| SV PSWN 88 (1200) | 88 North Pacesetter Way | Non-Lead - Other | | | Field inspection only (no records) | Non-Lead - Other | | Field inspection only (no records) | Non-Lead |
| SV PSWN 85,89,95 | 85 North Pacesetter Way | Non-Lead - Other | | | Field inspection only (no records) | Non-Lead - Other | | Field inspection only (no records) | Non-Lead |

| | | | | | | | | |
|----------------------|-------------------|---------------------|---|--|---------------------|------|--|----------|
| SV SALM 88 (1500) | 88 Salmon Way | Non-Lead - Other | | Installation record | Non-Lead - Other | | Diameter is 3 inches or more | Non-Lead |
| SV SALM 88 (1300) | 88 Salmon Way | Non-Lead - Other | | Field inspection only (no records) | Non-Lead - Other | | Field inspection only (no records) | Non-Lead |
| SV SALM 88 (1400) | 88 Salmon Way | Non-Lead - Other | | Field inspection only (no records) | Non-Lead - Other | | Field inspection only (no records) | Non-Lead |
| SV SALM 88 (1600) | 88 Salmon Way | Non-Lead - Other | | Installation record | Non-Lead - Other | 6 | Installation record | Non-Lead |
| SV SALM 109 | 109 Salmon Way | Non-Lead - Other | | Field inspection only (no records) | Non-Lead - Other | | Field inspection only (no records) | Non-Lead |
| SV SALM 88 (1700) | 88 Salmon Way | Non-Lead - Other | | Installation record | Non-Lead - Other | | Diameter is 3 inches or more | Non-Lead |
| SV SALM 141 | 141 Salmon Way | Non-Lead - Other | | Field inspection only (no records) | Non-Lead - Other | | Field inspection only (no records) | Non-Lead |
| SV SALM 88 (1900) | 88 Salmon Way | Non-Lead - Other | | Field inspection only (no records) | Non-Lead - Other | | Field inspection only (no records) | Non-Lead |
| SV SALM 169 | 169 Salmon Way | Non-Lead - Other | 6 | Installation record | Non-Lead - Other | | Diameter is 3 inches or more | Non-Lead |
| SV SALM 205 | 205 Salmon Way | Non-Lead - Other | 6 | Installation record | Non-Lead - Other | | Diameter is 3 inches or more | Non-Lead |
| SV SALM 281 | 281 Salmon Way | Non-Lead - Other | | Field inspection only (no records) | Non-Lead - Other | | Field inspection only (no records) | Non-Lead |
| SV SALM 244- 282 | 244 Salmon Way | Non-Lead - Other | 6 | Installation record | Non-Lead - PVC | 2 | Installation record | Non-Lead |
| SV SALM 314 | 314 Salmon Way | Non-Lead - Other | 6 | Installation record | Non-Lead - Other | | Diameter is 3 inches or more | Non-Lead |

| SV ABR 1745 | 1754 Airport Beach Rd. | Non-Lead - Copper | | | Field inspection only (no records) | Non-Lead - Copper | | Field inspection only (no records) | Non-Lead |
|---------------|---------------------------|----------------------|------------|-------|---|----------------------|---|--|----------|
| SV SALM 561 | 561 Salmon Way | Non-Lead - Copper | | | Repair / replacement record | Non-Lead - Copper | | Repair / replacement record | Non-Lead |
| SV ABR 1906 | 1906 Airport Beach Rd. | Non-Lead - Other | 5/28/2014 | 4 | Installation record | Non-Lead - Other | 4 | Diameter is 3 inches or more | Non-Lead |
| SV SALM 516 | 516 Salmon Way | Non-Lead - Copper | 4/6/1992 | 1 | Installation record | Non-Lead - Copper | | Repair / replacement record | Non-Lead |
| SV SALM 498 | 498 Salmon Way | Non-Lead - Other | 10/1/1992 | 6 | Installation record | Non-Lead - Other | 6 | Diameter is 3 inches or more | Non-Lead |
| SV SALM 487 | 487 Salmon Way | Non-Lead - Other | 2/25/1994 | 6 | Installation record | Non-Lead - Other | 6 | Diameter is 3 inches or more | Non-Lead |
| SV SALM 463 | 463 Salmon Way | Non-Lead - Other | | | Diameter is 3 inches or more | Non-Lead - Other | | Diameter is 3 inches or more | Non-Lead |
| SV SALM 400 | 400 Salmon Way | Non-Lead - Copper | | | Installation record | Non-Lead - Copper | | Repair / replacement record | Non-Lead |
| SV SELN 0 | 0 Sea Lion Circle | Non-Lead - Other | 10/3/2013 | | Installed after 1989 -AK lead ban | Non-Lead - Other | | Installed after 1989 -AK lead ban | Non-Lead |
| SV ABR 2000 | 2000 Airport Beach Rd. | Non-Lead - Copper | | 1 1/2 | Installation record | Non-Lead - Copper | | Repair / replacement record | Non-Lead |
| STUB ABR 1980 | 1980 Airport Beach Rd. | Non-Lead - Copper | | 1 | Installation record | N/A | | N/A | Non-Lead |
| SV EPNT 263 | 263 East Point Rd. | Non-Lead - Copper | 12/12/1990 | | Installation record | Non-Lead - Other | | Installed after 1989 -AK lead ban | Non-Lead |
| SV EPNT 256 | 256 East Point Rd. | Non-Lead - Copper | 11/16/1998 | 2 | Installation record | Non-Lead - Other | | Installed after 1989 -AK lead ban | Non-Lead |

| STUB EPNT 300 | 300 East Point Rd. | Non-Lead - Copper | 6/15/1998 | 3/4 | Installation record | N/A | | | N/A | Non-Lead |
|---------------|---------------------------|----------------------|------------|-----|---|----------------------|-----------|-----|---|----------|
| SV ABR 2387 | 2387 Airport Beach Rd. | Non-Lead - Other | 6/1/1997 | 6 | Installation record | Non-Lead - Other | | 6 | Diameter is 3 inches or more | Non-Lead |
| SV ABR 2315 | 2315 Airport Beach Rd. | Non-Lead - Other | | | Installed after 1989 -AK lead ban | Non-Lead - Other | | | Installed after 1989 -AK lead ban | #N/A |
| STUB ABR 2607 | 2607 Airport Beach Rd. | Non-Lead - Copper | 9/6/1995 | 3/4 | Installation record | N/A | | | N/A | Non-Lead |
| SV ABR 2568 | 2568 Airport Beach Rd. | Non-Lead - Copper | | 2 | Installation record | Non-Lead - Copper | | | Repair / replacement record | Non-Lead |
| SV ABR 2639 | 2639 Airport Beach Rd. | Non-Lead - Copper | 11/30/1990 | 3/4 | Installation record | Non-Lead - Copper | 6/25/2020 | 3/4 | Repair / replacement record | #N/A |
| SV ABR 2663 | 2663 Airport Beach Rd. | Non-Lead - Copper | | | Repair / replacement record | Non-Lead - Copper | | | Repair / replacement record | Non-Lead |
| SV ABR 2713 | 2713 Airport Beach Rd. | Non-Lead - Other | | 6 | Installation record | Non-Lead - Other | | 6 | Diameter is 3 inches or more | Non-Lead |
| SV TERM 79 | 79 Terminal Dr. | Non-Lead - Copper | 11/11/1991 | 1 | Repair / replacement record | Non-Lead - Copper | | 1 | Repair / replacement record | #N/A |
| SV TERM 105 | 105 Terminal Dr. | Non-Lead - Other | | | Diameter is 3 inches or more | Non-Lead - Other | | | Diameter is 3 inches or more | Non-Lead |
| SV ABR 2688 | 2688 Airport Beach Rd. | Non-Lead - Other | | | Diameter is 3 inches or more | Non-Lead - Other | | | Diameter is 3 inches or more | Non-Lead |
| SV ABR 2716 | 2716 Airport Beach Rd. | Non-Lead - Copper | | | Repair / replacement record | Non-Lead - Copper | | | Repair / replacement record | Non-Lead |
| SV ABR 2141 | 2141 Airport Beach Rd. | Non-Lead - Copper | 7/29/1995 | 1 | Installation record | Non-Lead - Copper | | 3/4 | Installation record | Non-Lead |

| STUB BIOR 20 | 20 Biorka Dr. | Non-Lead - Copper | | | Interpolation/ statistical | N/A | | N/A | Non-Lead |
|---------------|---------------------------|----------------------|-----------|-----|--|---------------------|--|---|----------|
| STUB BIOR 63 | 63 Biorka Dr. | Non-Lead - Copper | | | analysis Interpolation/ statistical analysis | N/A | | N/A | Non-Lead |
| SV BIOR 84 | 84 Biorka Dr. | Non-Lead - Copper | | | Installation record | Non-Lead - Other | | Interpolation/ statistical analysis | Non-Lead |
| SV BIOR 145 | 145 Biorka Dr. | Non-Lead - Copper | 11/1/1991 | 3/4 | Installation record | Non-Lead - HDPE | | Installation record | Non-Lead |
| SV BIOR 161 | 161 Biorka Dr. | Non-Lead - Other | | | Interpolation/ statistical analysis | Non-Lead - Other | | Interpolation/ statistical analysis | Non-Lead |
| SV BIOR 171 | 171 Biorka Dr. | Non-Lead - Other | | | Interpolation/ statistical analysis | Non-Lead - Other | | Interpolation/ statistical analysis | #N/A |
| SV STWB 57 | 57 Strawberry Hill Rd. | Non-Lead - Copper | | | Installation record | Non-Lead - Other | | Interpolation/ statistical analysis | #N/A |
| STUB BIOR 156 | 156 Biorka Dr. | Non-Lead - Copper | 8/12/1994 | 1 | Installation record | N/A | | N/A | Non-Lead |
| SV BIOR 180 | 180 Biorka Dr. | Non-Lead - Copper | 8/10/1994 | 1 | Installation record | Non-Lead - Other | | Installed after 1989 -AK lead ban | Non-Lead |
| STUB BIOR 201 | 201 Biorka Dr. | Non-Lead - Copper | | | Interpolation/ statistical analysis | N/A | | N/A | Non-Lead |
| STUB BIOR 190 | 190 Biorka Dr. | Non-Lead - Copper | | | Interpolation/ statistical analysis | N/A | | N/A | Non-Lead |
| SV BIOR 217 | 217 Biorka Dr. | Non-Lead - Other | | | Installation record | Non-Lead - Other | | Installation record | Non-Lead |
| SV KASH 33 | 33 Kashega Dr. | Non-Lead - Copper | 11/6/1991 | 3/4 | Installation record | Non-Lead - Other | | Installed after 1989 -AK lead ban | #N/A |

| SV KASH 63 | 63 Kashega Dr. | Non-Lead - Copper | 11/6/1991 | 3/4 | Installation record | Non-Lead - Other | | Installed after 1989 -AK lead ban | Non-Lead |
|---------------|---------------------|----------------------|------------|-----|---|----------------------|-----|---|----------|
| SV BIOR 271 | 271 Biorka Dr. | Non-Lead - Copper | 6/25/1991 | 1 | Installation record | Non-Lead - Copper | | Repair / replacement record | #N/A |
| STUB BIOR 280 | 280 Biorka Dr. | Non-Lead - Copper | 7/9/1991 | 1 | Repair / replacement record | N/A | | N/A | #N/A |
| SV BIOR 290 | 290 Biorka Dr. | Non-Lead - Copper | 8/15/2007 | 2 | Installation record | Non-Lead - Other | | Installed after 1989 -AK lead ban | Non-Lead |
| SV MAKU 77/79 | 77 Makushin Dr. | Non-Lead - Copper | 9/27/1993 | 1 | Installation record | Non-Lead - Other | | Installed after 1989 -AK lead ban | Non-Lead |
| SV MAKU 45 | 45 Maukshin Dr. | Non-Lead - Copper | 11/19/1990 | 3/4 | Installation record | Non-Lead - Copper | 3/4 | Installation record | Non-Lead |
| SV MAKU 61/63 | 61 Makushin Dr. | Non-Lead - Copper | | | Interpolation/ statistical analysis | Non-Lead - Other | | Interpolation/ statistical analysis | Non-Lead |
| SV MAKU 68 | 68 Makushin Dr. | Non-Lead - Copper | 6/11/2013 | 1 | Interpolation/ statistical analysis | Non-Lead - Other | | Installed after 1989 -AK lead ban | #N/A |
| SV MAKU 208 | 208 Makushin Dr. | Non-Lead - Copper | | 1 | Installation record | Non-Lead - Copper | | Field inspection only (no records) | Non-Lead |
| SV MAKU 218 | 218 Makushin Dr. | Non-Lead - Copper | 10/21/1993 | 3/4 | Installation record | Non-Lead - Other | | Installed after 1989 -AK lead ban | Non-Lead |
| SV KASC 51/53 | 51 Kashega Ct. | Non-Lead - Copper | | 1 | Installation record | Non-Lead - Other | | Other - describe in notes | Non-Lead |
| SV KASC 55/57 | 55 Kashega Ct. | Non-Lead - Copper | | | Interpolation/ statistical analysis | Non-Lead - Other | | Interpolation/ statistical analysis | Non-Lead |
| SV KASC 35/37 | 35 Kashega Ct. | Non-Lead - Copper | | 1 | Interpolation/ statistical analysis | Non-Lead - Other | | Interpolation/ statistical analysis | Non-Lead |

| SV KASH 70 | 70 Kashega Dr. | Non-Lead - Copper | 12/17/2014 | 1 | Installation record | Non-Lead - Other | 12/17/2014 | 1 | Installed after 1989 -AK lead ban | Non-Lead |
|--------------------|--------------------|----------------------|------------|---|---|----------------------|------------|---|---|----------|
| SV KASH 128/130 | 128 Kashega Dr. | Non-Lead - Copper | | | Interpolation/ statistical analysis | Non-Lead - Other | | | Interpolation/ statistical analysis | Non-Lead |
| SV KASH 112/114 | 112 Kashega Dr. | Non-Lead - Copper | 10/16/1993 | 1 | Installation record | Non-Lead - Other | | | Installed after 1989 -AK lead ban | Non-Lead |
| SV KASH 144/146 | 144 Kashega Dr. | Non-Lead - Copper | | | Interpolation/ statistical analysis | Non-Lead - Other | | | Interpolation/ statistical analysis | Non-Lead |
| SV KASH 160 | 160 Kashega Dr. | Non-Lead - Copper | | | Interpolation/ statistical analysis | Non-Lead - Other | | | Interpolation/ statistical analysis | Non-Lead |
| SV KASH 176 | 176 Kashega Dr. | Non-Lead - Copper | | | Interpolation/ statistical analysis | Non-Lead - Copper | | | Interpolation/ statistical analysis | Non-Lead |
| SV KASH 229/231 | 229 Kashega Dr. | Non-Lead - Copper | | | Interpolation/ statistical analysis | Non-Lead - Copper | | | Interpolation/ statistical analysis | Non-Lead |
| SV KASH 211/213 | 211 Kashega Dr. | Non-Lead - Copper | | 1 | Interpolation/ statistical analysis | Non-Lead - Copper | | | Interpolation/ statistical analysis | Non-Lead |
| SV KASH 193/195 | 193 Kashega Dr. | Non-Lead - Copper | | 1 | Interpolation/ statistical analysis | Non-Lead - Copper | | | Interpolation/ statistical analysis | Non-Lead |
| SV KASH 177/179 | 177 Kashega Dr. | Non-Lead - Copper | | 1 | Interpolation/ statistical analysis | Non-Lead - Copper | | | Interpolation/ statistical analysis | Non-Lead |
| SV KASH 161/163 | 161 Kashega Dr. | Non-Lead - Copper | | | Interpolation/ statistical analysis | Non-Lead - Copper | | | Interpolation/ statistical analysis | Non-Lead |
| SV KASH 145/147 | 145 Kashega Dr. | Non-Lead - Copper | | | Interpolation/ statistical analysis | Non-Lead - Copper | | | Interpolation/ statistical analysis | Non-Lead |
| SV KASH 129/131 | 129 Kashega Dr. | Non-Lead - Copper | | 1 | Interpolation/ statistical analysis | Non-Lead - Copper | | | Interpolation/ statistical analysis | Non-Lead |

| | | | | | | 1 | | |
|------------------------|-----------------------|----------------------|---|---|----------------------|---|---|----------|
| SV MAKU 121 | 121 Makushin Dr. | Non-Lead - Copper | 1 | Interpolation/ statistical analysis | Non-Lead - Copper | | Interpolation/ statistical analysis | Non-Lead |
| SV CHRN 46/48 | 46 Chernofshi Dr. | Non-Lead - Copper | 1 | Interpolation/ statistical analysis | Non-Lead - Copper | | Interpolation/ statistical analysis | Non-Lead |
| SV CHRN 32/34 | 32 Chernofski Dr. | Non-Lead - Copper | 1 | Interpolation/ statistical analysis | Non-Lead - Copper | | Interpolation/ statistical analysis | Non-Lead |
| SV CHRN 64/66 | 64 Chernofski Dr. | Non-Lead - Copper | 1 | Interpolation/ statistical analysis | Non-Lead - Copper | | Interpolation/ statistical analysis | Non-Lead |
| SV CHRN 98/100 | 98 Chernofski Dr. | Non-Lead - Copper | 1 | Interpolation/ statistical analysis | Non-Lead - Copper | | Interpolation/ statistical analysis | Non-Lead |
| SV CHRN 101 | 101 Chernofski Dr. | Non-Lead - Copper | 1 | Interpolation/ statistical analysis | Non-Lead - Copper | | Interpolation/ statistical analysis | Non-Lead |
| SV CHRN 114 | 114 Chernofski Dr. | Non-Lead - Copper | 1 | Interpolation/ statistical analysis | Non-Lead - Copper | | Interpolation/ statistical analysis | Non-Lead |
| SV CHRN 130/132 | 130 Chernofski Dr. | Non-Lead - Copper | 1 | Interpolation/ statistical analysis | Non-Lead - Copper | | Interpolation/ statistical analysis | Non-Lead |
| SV CHRN 113 | 113 Chernofski Dr. | Non-Lead - Copper | 1 | Interpolation/ statistical analysis | Non-Lead - Copper | | Interpolation/ statistical analysis | Non-Lead |
| SV CHRN 146 | 146 Chernofski Dr. | Non-Lead - Copper | | Interpolation/ statistical analysis | Non-Lead - Copper | | Interpolation/ statistical analysis | Non-Lead |
| SV CHRN 162/164 | 162 Chernofski Dr. | Non-Lead - Copper | 1 | Interpolation/ statistical analysis | Non-Lead - Copper | | Interpolation/ statistical analysis | Non-Lead |
| SV CHRN 176/178/180 | 176 Chernofski Dr. | Non-Lead - Copper | 1 | Interpolation/ statistical analysis | Non-Lead - Copper | | Interpolation/ statistical analysis | Non-Lead |
| SV CHRN 194 | 194 Chernofski Dr. | Non-Lead - Copper | 1 | Interpolation/ statistical analysis | Non-Lead - Copper | | Interpolation/ statistical analysis | Non-Lead |

| SV CHRN 210/212 | 210 Chernofski Dr. | Non-Lead - Copper | | | Interpolation/ statistical | Non-Lead - Copper | | | Interpolation/ statistical | Non-Lead |
|--------------------|-----------------------|----------------------|----------|-----|--|----------------------|----------|---|--|----------|
| SV CHRN 141/143 | 141 Chernofski Dr. | Non-Lead - Copper | | | analysis Interpolation/ statistical analysis | Non-Lead - Copper | | | analysis Interpolation/ statistical analysis | Non-Lead |
| SV CHRN 157/159 | 157 Chernofski Dr. | Non-Lead - Copper | | 1 | Interpolation/ statistical analysis | Non-Lead - Copper | | | Interpolation/ statistical analysis | Non-Lead |
| SV CHRN 173/175 | 173 Chernofski Dr. | Non-Lead - Copper | | 1 | Interpolation/ statistical analysis | Non-Lead - Copper | | | Interpolation/ statistical analysis | Non-Lead |
| SV CHRN 189/191 | 189 Chernofski Dr. | Non-Lead - Copper | | 1 | Interpolation/ statistical analysis | Non-Lead - Copper | | | Interpolation/ statistical analysis | Non-Lead |
| SV CHRN 205/207 | 205 Chernofski Dr. | Non-Lead - Copper | | | Interpolation/ statistical analysis | Non-Lead - Copper | | | Interpolation/ statistical analysis | Non-Lead |
| SV CHRN 221/223 | 221 Chernofski Dr. | Non-Lead - Copper | | 1 | Interpolation/ statistical analysis | Non-Lead - Copper | | | Interpolation/ statistical analysis | Non-Lead |
| SV CHRN 237/239 | 237 Chernofski | Non-Lead - Copper | | 1 | Interpolation/ statistical analysis | Non-Lead - Copper | | | Interpolation/ statistical analysis | Non-Lead |
| SV DLTA 186 | 186 Delta Way | Non-Lead - Copper | | 4 | Interpolation/ statistical analysis | Non-Lead - Copper | | 2 | Interpolation/ statistical analysis | Non-Lead |
| SV DLTA 42 | 42 Delta Way | Non-Lead - Copper | 9/4/2014 | 1 | Interpolation/ statistical analysis | Non-Lead - Copper | 9/4/2014 | 1 | Interpolation/ statistical analysis | Non-Lead |
| SV BIOR 420 | 420 Biorka Dr. | Non-Lead - Other | | 1 | Installed after 1989 -AK lead ban | Non-Lead - Other | | | Installed after 1989 -AK lead ban | Non-Lead |
| SV BIOR 438 | 438 Biorka Dr. | Non-Lead - Copper | 7/7/1990 | 3/4 | Interpolation/ statistical analysis | Non-Lead - Other | | | Installed after 1989 -AK lead ban | Non-Lead |
| SV BIOR 452 | 452 Biorka Dr. | Non-Lead - Copper | | | Interpolation/ statistical analysis | Non-Lead - Other | | | Interpolation/ statistical analysis | Non-Lead |

| SV BIOR 468 | 468 Biorka Dr. | Non-Lead - Copper | | 1 | Interpolation/ statistical analysis | Non-Lead - Other | Interpolation/ statistical analysis | Non-Lead |
|--------------------|---------------------|----------------------|-----------|-----|---|---------------------|---|----------|
| SV BIOR 484/486 | 484 Biorka Dr. | Non-Lead - Copper | | 1 | Interpolation/ statistical analysis | Non-Lead - Other | Interpolation/ statistical analysis | Non-Lead |
| SV BIOR 500/502 | 500 Biorka Dr. | Non-Lead - Copper | | 1 | Interpolation/ statistical analysis | Non-Lead - HDPE | Interpolation/ statistical analysis | Non-Lead |
| SV BIOR 510 | 510 Biorka Dr. | Non-Lead - Copper | | 1 | Installation record | Non-Lead - Other | Interpolation/ statistical analysis | Non-Lead |
| SV BIOR 519 | 519 Biorka Dr. | Non-Lead - Copper | | 1 | Installation record | Non-Lead - Other | Interpolation/ statistical analysis | Non-Lead |
| SV BIOR 522 | 522 Biorka Dr. | Non-Lead - Copper | | 1 | Installation record | Non-Lead - Other | Interpolation/ statistical analysis | Non-Lead |
| SV BIOR 534 | 534 Biorka Dr. | Non-Lead - Copper | | 1 | Installation record | Non-Lead - Other | Interpolation/ statistical analysis | Non-Lead |
| SV BIOR 537/539 | 537 Biorka Dr. | Non-Lead - Copper | 7/7/1997 | 1 | Installation record | Non-Lead - Other | Installed after 1989 -AK lead ban | Non-Lead |
| SV BIOR 529 | 529 Biorka Dr. | Non-Lead - Copper | 5/5/2006 | 3/4 | Installation record | Non-Lead - Other | Installed after 1989 -AK lead ban | Non-Lead |
| SV Maku 255 | 255 Makushin. | Non-Lead - Copper | | 1 | Installation record | Non-Lead - Other | Installed after 1989 -AK lead ban | Non-Lead |
| SV BIOR 615 | 615 Biorka Dr. | Non-Lead - Copper | 8/12/2002 | 3/4 | Installation record | Non-Lead - Other | Installed after 1989 -AK lead ban | Non-Lead |
| SV BIOR 662 | 662 Biorka Dr. | Non-Lead - Copper | | | Interpolation/ statistical analysis | Non-Lead - Other | Interpolation/ statistical analysis | Non-Lead |
| SV DRFT 28 | 28 Driftwood Way | Non-Lead - Copper | | 1 | Installation record | Non-Lead - Other | Interpolation/ statistical analysis | Non-Lead |

| SV DRFT 19 | 19 Driftwood Way | Non-Lead - Copper | | | Interpolation/ statistical analysis | Non-Lead - Other | Interpolation/ statistical analysis | Non-Lead |
|------------|---------------------|----------------------|-----------|-----|---|---------------------|---|----------|
| SV DRFT 17 | 17 Driftwood Way | Non-Lead - Copper | | | Interpolation/ statistical analysis | Non-Lead - Other | Interpolation/ statistical analysis | Non-Lead |
| SV DRFT 51 | 51 Driftwood Way | Non-Lead - Copper | 7/5/1990 | 3/4 | Installation record | Non-Lead - Other | Installed after 1989 -AK lead ban | Non-Lead |
| SV DORA 24 | 24 Dora Circle | Non-Lead - Copper | 7/18/1990 | 3/4 | Installation record | Non-Lead - Other | Installed after 1989 -AK lead ban | Non-Lead |
| SV DORA 28 | 28 Dora Circle | Non-Lead - Copper | 7/18/1990 | 3/4 | Installation record | Non-Lead - Other | Installed after 1989 -AK lead ban | Non-Lead |
| SV DORA 32 | 32 Dora Circle | Non-Lead - Copper | 7/18/1990 | 3/4 | Installation record | Non-Lead - Other | Installed after 1989 -AK lead ban | Non-Lead |
| SV DORA 36 | 36 Dora Circle | Non-Lead - Copper | 7/18/1990 | 3/4 | Installation record | Non-Lead - Other | Installed after 1989 -AK lead ban | Non-Lead |
| SV DORA 40 | 40 Dora Circle | Non-Lead - Copper | 7/18/1990 | 3/4 | Installation record | Non-Lead - Other | Installed after 1989 -AK lead ban | Non-Lead |
| SV DORA 23 | 23 Dora Circle | Non-Lead - Copper | 7/18/1990 | 3/4 | Installation record | Non-Lead - Other | Installed after 1989 -AK lead ban | Non-Lead |
| SV DORA 27 | 27 Dora Circle | Non-Lead - Copper | 7/18/1990 | 3/4 | Installation record | Non-Lead - Other | Installed after 1989 -AK lead ban | Non-Lead |
| SV DORA 31 | 31 Dora Circle | Non-Lead - Copper | 7/18/1990 | 3/4 | Installation record | Non-Lead - Other | Installed after 1989 -AK lead ban | Non-Lead |
| SV DORA 35 | 35 Dora Circle | Non-Lead - Copper | 7/18/1990 | 3/4 | Installation record | Non-Lead - Other | Installed after 1989 -AK lead ban | Non-Lead |
| SV DORA 39 | 39 Dora Circle | Non-Lead - Copper | 7/18/1990 | 3/4 | Installation record | Non-Lead - Other | Installed after 1989 -AK lead ban | Non-Lead |

| SV DORA 6 | 6 Dora Circle | Non-Lead - | 7/18/1990 | 3/4 | Installation , | Non-Lead - | | Installed after 1989 -AK lead | Non-Lead |
|--------------------|---------------------------|----------------------|------------|-----|---|----------------------|-----|---|----------|
| | | Copper | | | record | Other | | ban | |
| SV DORA 10 | 10 Dora Circle | Non-Lead - Copper | 7/18/1990 | 3/4 | Installation record | Non-Lead - Other | | Installed after 1989 -AK lead ban | Non-Lead |
| SV DORA 14 | 14 Dora Circle | Non-Lead - Copper | 7/18/1990 | 3/4 | Installation record | Non-Lead - Other | | Installed after 1989 -AK lead ban | Non-Lead |
| SV DORA 18 | 18 Dora Circle | Non-Lead - Copper | 7/18/1990 | 3/4 | Installation record | Non-Lead - Other | | Installed after 1989 -AK lead ban | Non-Lead |
| SV DORA 22 | 22 Dora Circle | Non-Lead - Copper | 7/18/1990 | 3/4 | Installation record | Non-Lead - Other | | Installed after 1989 -AK lead ban | Non-Lead |
| SV DRFT 197/199 | 197 Dirftwood Way | Non-Lead - Copper | | 2 | Repair / replacement record | Non-Lead - Other | | Field inspection only (no records) | Non-Lead |
| SV EPNT 30 | 30 East Point Rd. | Non-Lead - Copper | | 1 | Interpolation/ statistical analysis | Non-Lead - Other | | Interpolation/ statistical analysis | Non-Lead |
| SV ABR 2029 | 2029 Airport Beach Rd. | Non-Lead - Other | 9/1/1993 | 6 | Installation record | Non-Lead - Other | | Diameter is 3 inches or more | Non-Lead |
| SV EPNT 60 | 60 East Point Rd. | Non-Lead - Copper | 4/7/1998 | 3/4 | Installation record | Non-Lead - Other | | Installed after 1989 -AK lead ban | Non-Lead |
| SV EPNT 365 | 365 East Point Rd. | Non-Lead - Copper | 11/15/2014 | 2 | Installation record | Non-Lead - Other | | Installed after 1989 -AK lead ban | Non-Lead |
| SV EPNT 388 | 388 East Point Rd. | Non-Lead - Copper | | 1 | Installation record | Non-Lead - Other | | Installed after 1989 -AK lead ban | Non-Lead |
| STUB EPNT 430 | 430 East Point Rd. | Non-Lead - Copper | 10/12/1996 | | Installation record | N/A | | N/A | Non-Lead |
| SV EPNT 440/442 | 440 East Point Rd. | Non-Lead - Copper | 7/9/2013 | 3/4 | Installation record | Non-Lead - Copper | 3/4 | Other - describe in notes | Non-Lead |

| SV EPNT 441 | 441 East Point Rd. | Non-Lead - Copper | 6/2/2006 | 3/4 | Installation record | Non-Lead - Other | Installed after 1989 -AK lead ban | Non-Lead |
|---|------------------------|----------------------|-----------|-----|---|----------------------|---|----------|
| SV EPNT 467 | 467 East Point Rd. | Non-Lead - Copper | | | Interpolation/ statistical analysis | Non-Lead - Copper | Field inspection only (no records) | Non-Lead |
| SV EPNT 504 | 504 East Point Rd. | Non-Lead - Copper | 1/20/1998 | 1 | Installation record | Non-Lead - Other | Installed after 1989 -AK lead ban | Non-Lead |
| SV EPNT 583 | 583 East Point Rd. | Non-Lead - Other | | 6 | Installation record | Non-Lead - Other | Diameter is 3 inches or more | #N/A |
| SV EPNT 601 | 601 East Point Rd. | Non-Lead - Other | | 4 | Installation record | Non-Lead - Other | Diameter is 3 inches or more | Non-Lead |
| SV BEND 10/28 | 10 Bendiksen Rd. | Non-Lead - Other | | | Installed after 1989 -AK lead ban | Non-Lead - Other | Installed after 1989 -AK lead ban | Non-Lead |
| SV BEND 36/38/40/44/48 /50/52/54/56 | 36 Bendiksen Rd. | Non-Lead - Other | 4/19/1991 | | Installation record | Non-Lead - Other | Diameter is 3 inches or more | Non-Lead |
| STUB EPNT 954 | 954 East Point Rd. | Non-Lead - Copper | | | Installation record | N/A | N/A | Non-Lead |
| SV EPNT 1125 | 1125 East Point Rd. | Non-Lead - Other | | 6 | Installation record | Non-Lead - Other | Diameter is 3 inches or more | Non-Lead |
| STUB EPNT 1127 | 1127 East Point Rd. | Non-Lead - Copper | | 1 | Installation record | N/A | N/A | Non-Lead |
| SV EPNT 1068/1084 | 1068 East Point Rd. | Non-Lead - Copper | | | Repair / replacement record | Non-Lead - HDPE | Field inspection only (no records) | Non-Lead |
| SV EPNT 1410 | 1410 East Point Rd. | Non-Lead - Copper | | | Repair / replacement record | Non-Lead - Other | Interpolation/ statistical analysis | Non-Lead |
| SV EPNT 1577 | 1577 East Point Rd. | Non-Lead - Copper | | 2 | Installation record | Non-Lead - Other | Interpolation/ statistical analysis | #N/A |

| SV EPNT 1530 | 1530 East Point Rd. | Non-Lead - Other | | 1 | Interpolation/ statistical analysis | Non-Lead - HDPE | | Repair / replacement record | Non-Lead |
|-------------------|------------------------|----------------------|-----------|-----|---|----------------------|---|---|----------|
| SV EPNT 1558 | 1558 East Point Rd. | Non-Lead - Copper | 1/3/1990 | 1 | Installation record | Non-Lead - Copper | | Installation record | #N/A |
| SV EPNT 1560 | 1560 East Point Rd. | Non-Lead - Copper | 12/9/1991 | 1 | Installation record | Non-Lead - Other | | Installed after 1989 -AK lead ban | Non-Lead |
| SV EPNT 1532 | 1532 East Point Rd. | Non-Lead - Other | 12/3/1990 | | Installed after 1989 -AK lead ban | Non-Lead - Other | | Installed after 1989 -AK lead ban | Non-Lead |
| SV EPNT 1434 | 1434 East Point Rd. | Non-Lead - Copper | | | Repair / replacement record | Non-Lead - Copper | | Repair / replacement record | Non-Lead |
| SV DLTA 152 | 152 Delta Way | Non-Lead - Copper | 6/8/2005 | 3/4 | Installation record | Non-Lead - Other | | Installed after 1989 -AK lead ban | Non-Lead |
| SV EPNT 1589 | 1589 East Point Rd. | Non-Lead - Copper | 2/20/1992 | 1 | Installation record | Non-Lead - Other | | Installed after 1989 -AK lead ban | Non-Lead |
| SV DLTA 18 | 18 Delta Way | Non-Lead - Copper | 6/19/1991 | 2 | Installation record | Non-Lead - Other | | Installed after 1989 -AK lead ban | Non-Lead |
| SV EPNT 1617 | 1617 East Point Rd. | Non-Lead - Other | 6/10/2013 | 8 | Installation record | Non-Lead - Other | 8 | Diameter is 3 inches or more | Non-Lead |
| SV EPNT 1619 | 1619 East Point Rd. | Non-Lead - Other | 6/9/2013 | 6 | Installation record | Non-Lead - Other | 6 | Diameter is 3 inches or more | Non-Lead |
| STUB EPNT 1634 | 1634 East Point Rd. | Non-Lead - Copper | | 2 | Repair / replacement record | N/A | | N/A | Non-Lead |
| SV EPNT 1700 | 1700 East Point Rd. | Non-Lead - Other | | | Diameter is 3 inches or more | Non-Lead - Other | | Diameter is 3 inches or more | Non-Lead |
| SV EPNT 1732 | 1732 East Point Rd. | Non-Lead - Other | | 4 | Installation record | Non-Lead - Other | | Diameter is 3 inches or more | Non-Lead |

| SV BAL 80/90 | 80 Ballyhoo Rd. | Non-Lead - Other | 9/1/1990 | 3/4 | Installed after 1989 -AK lead ban | Non-Lead - Other | | | Installed after 1989 -AK lead ban | Non-Lead |
|----------------|----------------------|----------------------|-----------|-----|---|----------------------|-----------|-----|---|----------|
| SV BAL 100 | 100 Ballyhoo Rd. | Non-Lead - Other | 9/1/1990 | 2 | Installed after 1989 -AK lead ban | Non-Lead - Other | | | Installed after 1989 -AK lead ban | Non-Lead |
| SV TUND 100 | 100 Tundra Dr. | Non-Lead - Copper | 1/27/1994 | 3/4 | Installation record | Non-Lead - Other | | | Installed after 1989 -AK lead ban | #N/A |
| SV BAL 644 | 644 Ballyhoo Rd. | Non-Lead - Copper | 7/1/1990 | 3/4 | Installation record | Non-Lead - Other | | | Installed after 1989 -AK lead ban | Non-Lead |
| SV BAL 639/647 | 647 Ballyhoo Rd. | Non-Lead - Copper | 11/4/1992 | 3/4 | Installation record | Non-Lead - Copper | 11/4/1992 | 3/4 | Installation record | Non-Lead |
| SV BAL 723 | 723 Ballyhoo Rd. | Non-Lead - Copper | | | Installed after 1989 -AK lead ban | Non-Lead - Copper | | | Installed after 1989 -AK lead ban | Non-Lead |
| SV BAL 748 | 748 Ballyhoo Rd. | Non-Lead - Copper | 5/18/1992 | 2 | Installation record | Non-Lead - Copper | | 2 | Installation record | Non-Lead |
| SV BAL 750 | 750 Ballyhoo Rd. | Non-Lead - Copper | 5/18/1992 | 2 | Installation record | Non-Lead - Other | | | Installed after 1989 -AK lead ban | Non-Lead |
| SV BAL 731 | 731 Ballyhoo Rd. | Non-Lead - Other | 5/22/2002 | 6 | Installation record | Non-Lead - Other | | 6 | Diameter is 3 inches or more | Non-Lead |
| SV BAL 939 | 939 Ballyhoo Rd. | Non-Lead - Other | | 6 | Installation record | Non-Lead - Other | | 6 | Diameter is 3 inches or more | Non-Lead |
| SV BAL 991 | 991 Ballyhoo Rd. | Non-Lead - Other | 11/1/1990 | | Installation record | Non-Lead - Other | | | Diameter is 3 inches or more | Non-Lead |
| SV ULAT 184 | 184 Ulatka Dr. | Non-Lead - Copper | | 3/4 | Installation record | Non-Lead - HDPE | | 1 | Installation record | Non-Lead |
| SV BAL 1362 | 1362 Ballyhoo Rd. | Non-Lead - Copper | | 1 | Installation record | Non-Lead - Copper | | | Repair / replacement record | Non-Lead |

| SV BAL 1364 | 1364 Ballyhoo Dr. | Non-Lead - Other | | 6 | Installation record | Non-Lead - Other | 6 | Diameter is 3 | Non-Lead |
|---------------|----------------------|----------------------|------------|-------|---|----------------------|---|---|----------|
| SV BAL 1503 | 1503 Ballyhoo Rd. | Non-Lead - Other | 7/7/2008 | 8 | Installation record | Non-Lead - Other | 8 | Diameter is 3 inches or more | Non-Lead |
| SV BAL 1505 | 1505 Ballyhoo Rd. | Non-Lead - Other | 7/7/2008 | 4 | Installation record | Non-Lead - Other | 4 | Diameter is 3 inches or more | Non-Lead |
| SV BAL 1653 | 1653 Ballyhoo Rd. | Non-Lead - Copper | 6/1/1990 | 2 | Installation record | Non-Lead - Other | | Installed after 1989 -AK lead ban | Non-Lead |
| SV BAL 1654 | 1654 Ballyhoo Rd. | Non-Lead - Copper | 6/1/1990 | 1 1/2 | Installation record | Non-Lead - Other | | Installed after 1989 -AK lead ban | Non-Lead |
| SV BAL 1712 | 1712 Ballyhoo Rd. | Non-Lead - Copper | 11/22/2005 | 3/4 | Installation record | Non-Lead - Other | | Installed after 1989 -AK lead ban | Non-Lead |
| SV BAL 1787 | 1787 Ballyhoo Rd. | Non-Lead - Copper | 6/1/1990 | 2 | Installation record | Non-Lead - Other | | Installed after 1989 -AK lead ban | Non-Lead |
| SV BAL 1829 | 1829 Ballyhoo Rd. | Non-Lead - Other | 6/1/1990 | 6 | Installation record | Non-Lead - Other | 6 | Diameter is 3 inches or more | Non-Lead |
| STUB BAL 1855 | 1855 Ballyhoo Rd. | Non-Lead - Other | | | Interpolation/ statistical analysis | N/A | | N/A | Non-Lead |
| SV BAL 1896 | 1896 Ballyhoo Rd. | Non-Lead - Copper | 6/1/1990 | | Repair / replacement record | Non-Lead - Copper | | Repair / replacement record | Non-Lead |
| SV BAL 1850 | 1850 Ballyhoo Rd. | Non-Lead - Copper | 6/1/1990 | | Repair / replacement record | Non-Lead - Copper | | Repair / replacement record | Non-Lead |
| SV BAL 2481 | 2481 Ballyhoo Rd. | Non-Lead - Other | 11/27/2001 | | Installation record | Non-Lead - Other | | Diameter is 3 inches or more | Non-Lead |
| SV BAL 2633 | 2633 Ballyhoo Rd. | | | | | | | | |